

ATTACHMENT C: Photograph Log

Cypress Pit

Bama Concrete Products Company, Inc.
dba Davis Sand and Gravel

Cypress, Alabama
April 26-27, 2023

N



Overview Map





Title	Photo 1
Comment	Taken by Rachel Earwood on April 25, 2023
Description	Striking northeast, east. Black Warrior River, looking upstream toward the site. Red arrows in top photo indicates direction of flow.



Title	Photo 4*
Comment	Taken by Rachel Earwood
Description	Crawfish burrow in vicinity of reference area, which is displayed in Photos 5 and 6.

*Based on a lack of connectivity, location information is not available for this image and the time stamp is incorrect.



Title	Photo 2
Comment	Taken by Rachel Earwood
Description	Striking southeast; upstream. Outfall per the NPDES permit. Skimmer in the bottom righthand corner of image. Red arrow in top photo indicates direction of flow.



Title	Photo 3
Comment	Taken by Rachel Earwood
Description	Striking west, northwest; downstream. NPDES outfall. Red arrow in top photo indicates direction of flow.



Title	Photo 5
Comment	Taken by Rachel Earwood
Description	Striking west, over approximate location of data point S1.



Title	Photo 6
Comment	Taken by Rachel Earwood
Description	Striking east, over approximate location of data point S1.



Title	Photo 7
Comment	Taken by Rachel Earwood
Description	Striking south, southwest. View of pond, “Pond 3” (per NPDES permit) that feeds outfall.



Title	Photo 8
Comment	Taken by Rachel Earwood
Description	Striking southeast. Pond 3, pointing in a direction closer to the outfall.



Title	Photo 9
Comment	Taken by Rachel Earwood
Description	Striking north. Historical exploration/extraction area pertaining to a local methane concern, periodically fed by Pond 4.



Title	Photo 10
Comment	Taken by Rachel Earwood
Description	Striking northeast. Methane exploration/extraction area, looking in direction of Pond 4.




Title	Photo 11
Comment	Taken by Rachel Earwood
Description	Striking south, southwest. Obligate wetland vegetation growing in cove area potentially created by a berm breach.




Title	Photo 12
Comment	Taken by Rachel Earwood
Description	Striking east, southeast. Taken from the breached berm, looking toward a wetland system beyond the permitted limits of settling Pond 4.



Title	Photo 13
Comment	Taken by Rachel Earwood
Description	Soil profile, data point S2.



Title	Photo 14
Comment	Taken by Rachel Earwood
Description	Striking west, over data point S2.



Title	Photo 15
Comment	Taken by Rachel Earwood
Description	Striking east, southeast, over data point S2.




Title	Photo 16
Comment	Taken by Rachel Earwood
Description	Striking northeast. Facility's new dredge. Material dredging actively taking place in cell directly south of Cutoff Road.



Title	Photo 17
Comment	Taken by Rachel Earwood
Description	Striking east. Broad view of active dredging location, material sorter in the background.



Title	Photo 18
Comment	Taken by Rachel Earwood
Description	Striking southeast. Continuation of active dredging location.



Title	Photo 19
Comment	Taken by Rachel Earwood
Description	Striking south, southeast, over data point S3.




Title	Photo 20
Comment	Taken by Rachel Earwood
Description	Striking north, over data point S3.



Title	Photo 21
Comment	Taken by Rachel Earwood
Description	Soil profile, data point S4.



Title	Photo 22
Comment	Taken by Rachel Earwood
Description	Striking north, over data point S4.



Title	Photo 23
Comment	Taken by Rachel Earwood
Description	Striking southeast, over data point S4.



Title	Photo 24
Comment	Taken by Lonnie Dorn
Description	Signage at the facility's entrance. Note NPDES permit information.

PAGE INTENTIONALLY LEFT BLANK