

EXXON COMPANY, U.S.A.

POST OFFICE BOX 1512 • HOUSTON, TEXAS 77001 "EUSAMARINE HOUSTON"

MARINE DEPARTMENT

J. H. SWARTZ
OPERATIONS MANAGER

A. D. MOOKHOEK
FLEET & BRANCH MANAGER

L. H. EARLE
MARINE ADVISOR

H. J. BORGES
MAINTENANCE & SERVICES MANAGER

December 5, 1978

FILE

Mr. Scotty McIntosh
USMP Company, Incorporated
150 Lynhurst Avenue
Staten Island, New York 10305

Dear Scotty:

Enclosed, you will find photographs I have taken at Newport News Shipyard showing the old and overhauled rotating elements of the Warren feed pump aboard the EXXON WASHINGTON. As you can see, the pressure reducing ring PC.13 and channel ring PC. 17 are assembled in the wrong sequence, and in no way would the element fit down into the casing. I have marked the tangs in white chalk, so they would stand out. I had the shipyard disassemble the two end impellers and reverse the sequence with the Warren feed pump service engineer in attendance.

As per our telephone conversation, I am forwarding these photographs.

Regards,

John McCracken
John McCracken
Repair Inspector

JMCC: bt
Enclosure

JML
c: Mr. H. P. Leyendecker w/attachments
Mr. E. J. Worrel, Jr. w/attachments



