

Inspection Report Addendum for Well: MT20000-01111
Inspection Date: 10/25/2023

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20000-01111 (101-W4), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/25/2023			
Photo No. 1 of 3	Time: 10:11 am		
Photo Description: Wellhead was observed to be disconnected from pipe flowline (left of the wellhead).			

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20000-01111 (101-W4), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/25/2023			
Photo No. 2 of 3	Time: 10:13 am		
Photo Description: Operator opened tubing master ball valve to check tubing pressure. Well showed no pressure in tubing. Records show operator reported mechanical integrity loss on the well on 2/27/2023. EPA responded with Notice of non-compliance letter on 3/2/2023. No follow up correspondence regarding mechanical integrity status since NON issuance.			

Inspection Report Addendum for Well: MT20000-01111
Inspection Date: 10/25/2023

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20000-01111 (101-W4), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/25/2023			
Photo No. 3 of 3	Time: 10:11 am		
Photo Description: Tubing-casing annulus observed to be maintained continuously open to atmospheric pressure.			

 Inspector signature

 Inspector signature

 Inspector signature