


Inspection Report Addendum for Well: MT20000-01131
Inspection Date: 10/24/2023

d

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20000-01131 (71-W1), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/24/2023			
Photo No. 1 of 4	Time: 4:33 pm		
Photo Description: Well sign by wellhead.			

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20000-01131 (71-W1), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/24/2023			
Photo No. 2 of 4	Time: 4:33 pm		
Photo Description: Wellhead is observed to be disconnected from flowline (behind the wellhead).			

Inspection Report Addendum for Well: MT20000-01131
Inspection Date: 10/24/2023

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20000-01131 (71-W1), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/24/2023			
Photo No. 3 of 4	Time: 4:33 pm		
Photo Description: Tubing valve was frozen shut during inspection and operator was unable to open valve. Tubing pressure was not checked. Operator noted that they will get pumper to thaw open the valve and return to the well to check the tubing pressure values the next day. Inspector did not return to well to recheck value.			

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20000-01131 (71-W1), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/24/2023			
Photo No. 4 of 4	Time: 4:33 pm		
Photo Description: Tubing-casing annulus observed to be maintained continuously open to atmospheric pressure.			

LIANG
 Digitally signed
 by LIANG WANG
 Date: 2023.11.20
 09:08:37 -07'00'
WANG

Inspector signature

Inspector signature

Inspector signature