

Well Inspection
Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Jeanne Eckhart	Inspection Date	02/22/2023	Time	08:30
Inspection Due	2024-01-12T00:00:00Z	Operator Representative	Binger Operations, LLC		
Operator Info	Binger Operations, LLC 204 North Robinson, Suite 2300 Oklahoma City, OK 731026891 Phone: 405-687-0855	Inventory ID	OK0118000		
		API Well No			
		Lease Name	E Binger Un (Cook D-1)		
		Well ID	58-GI-1		
Location	SE 31 10N 10W	Status	Active	Well Type	Enhanced Recovery
Latitude	35.291333	Longitude	-98.29045		
Inspection Reason	MIT	Responsible Company at Time of Inspection	Binger Operations, LLC		
Inspect No.		Date Last MIT	01/12/2022	Last Test Result	A
Casing	5.5	Tubing	2.375	USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	Y	Y	Max Pressure 5000
FLM Canister Pressure		Actual Pressure	4100		Max Volume
Lease Status	Active	Determined?	Compan y Gage		Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	Y				
Inspection Comments	Inspectors Matthew Allen, Jeanne Eckhart, and Tamara Griffin witnessed a Standard Annulus Pressure Test (SAPT) on well OK0118000. Injection pressure increased over 10% for three attempt to hold pressure consistently while conducting the SAPT. The increasing casing pressure during the SAPT is an area of concern. This well was being used for injection at the time of the inspection. EPA enforcement staff will review this inspection data to determine compliance with EPA UIC regulations.				
Inspector Signature	JEANNE ECKHART Digitally signed by JEANNE ECKHART Date: 2023.03.21 09:12:57 -05'00'				
Supervisor Signature	DAMON MCELROY Digitally signed by DAMON MCELROY DN: c=US, o=U.S. Government, ou=Environmental Protection Agency, cn=DAMON MCELROY, 0.9.2342.19200300.100.1.1=68001003655653 Date: 2023.03.27 12:56:44 -05'00'				

Appendix 1

Photograph Log

2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 35.291333, -98.29045		
City: Binger	County/Parish: Caddo	State: Oklahoma



Photo File Name: R0010002.JPG

Orientation: E

Date of Photo: 02/22/2023

Time of Photo: 8:41 AM

Latitude: 35.291333

Longitude: -98.29045

Photographer: Tamara Griffin

Description: This was the injection well OK0118000 sign at the time of the inspection.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 35.291333, -98.29045		
City: Binger	County/Parish: Caddo	State: Oklahoma




Photo File Name: R0010004.JPG

Orientation: SE

Date of Photo: 02/22/2023

Time of Photo: 8:53 AM

Latitude: 35.286567

Longitude: -98.304183

Photographer: Tamara Griffin

Description: This was the injection well OK0117000 at the time of the inspection.