

FRICTION MATERIALS STANDARDS INSTITUTE, 588 MONROE TURNPIKE, MONROE, CT 06468
 A U T O M O T I V E D A T A B U L L E T I N #3-951
 January 24, 1996

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>ACURA</u>			
1996, Integra	7493-D617**	D/D	7443-D564**
1996, TL	7382-D503**	D/D	7418-D536**
<u>AUDI</u>			
1996, A6	7306-D419**	D/D	7309-D228**
OR	7434-D555**	D/	
<u>BMW (See Comments & Corrections)</u>			
1996, 318i	7437-D558**	D/D	7567-D692** (Notes #9 & #25)
1996, 325i	7437-D558**	D/D	7567-D692**
1995-94, 318i		/D	7567-D692**
1995-94, 325 i		/D	7567-D692**
1995, 740i	7560-D681**	D/D	7427-D683**
	(Notes #2 & #15)		(Note #17)
1995, 740iL	7560-D681**	D/D	7427-D683**
1995, 750iL	7561-D682**	D/D	7427-D683**
	(Notes #3 & #16)		
<u>FORD</u>			
1996, Crown Victoria	7537-D678**	D/D	7565A-D690 (Notes #7 & #23)
1996, Crown Victoria Police	7537-D678**	D/D	7555-D674**
<u>GEO</u>			
1996, Tracker 2DR	7305-D418**	D/N	1491-S710* (Notes #11 & #28)
1996, Tracker 4DR	7435-D556**	D/N	1492-S711* (Notes #12 & #29)
<u>HONDA</u>			
1996, Accord Coupe	7345-D465**	D/N	1429-S627*
OR		/D	7418-D537**
1996, Accord Sedan	7345-D465**	D/N	1429-S627*
OR		/D	7418-D537**
1996, Accord Wagon	7382-D503**	D/N	1429-S627*
OR		/D	7418-D537**
1996, Prelude	7448-D568**	D/D	7418-D537**
OR	7382-D503**	D/	
1996, Odyssey	7382-D503**	D/D	7418-D536**

SEE DISCLAIMER AT END OF BULLETIN

FMSI® and FMS® are registered trademarks of the Friction Materials Standards Institute, Inc.

Copyright© by Friction Materials Standards Institute, Inc.

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>JAGUAR</u>			
1995, XJ6		/D	7563-D688** (Notes #5 & #21)
1995, XJ12		/D	7563-D688**
1995, XJR		/D	7563-D688**
1995, XJS		/D	7563-D688**
<u>KIA (See Comments)</u>			
1996, Sephia	7529-D649**	D/N	1493-S697* (Note #13)
OR		/D	7568-D693** (Notes #10 & #26)
<u>MERCEDES</u>			
1995-94, S320	7564-D689**	D/ (Notes #6 & #22)	
1995-94, S350TD	7564-D689**	D/D	7526-D603**
1995-94, S420	7564-D689**	D/	
1995-94, S500	7564-D689**	D/	
1995-94, S600	7564-D689**	D/	
<u>MERCURY</u>			
1996, Grand Marquis	7537-D678**	D/D	7565A-D690
1996, Grand Marquis Police	7537-D678**	D/D	7555-D674**
<u>NISSAN</u>			
1996, Altima	7407-D526**	D/N	1457-S671*
OR		/D	7421-D595**
1996, Maxima	7318-D653**	D/D	7533-D640**
OR	7407-D526**	D/	
1996, Sentra	7546-D668**	D/N	1438-S638*
OR		/D	7547-D669**
1996, 200SX	7546-D668**	D/N	1438-S638*
OR		/D	7547-D669**
1996, Quest	7546-D576**	D/N	1452-S665*
1996, Pathfinder	7566-D691**	D/N	1433-S631*
	(Notes #8 & #24)		
<u>PLYMOUTH</u>			
1996, Breeze	7530A-D650	D/N	1481-S698*
OR		/D	7438B-D641
1996, Neon	7511A-D633	D/N	1473-S689*
OR	7518A-D642	D/D	7438B-D641
<u>PORSCHE</u>			
1996, 911 Carrera Targa	7327-D609**	D/D	7326-D446**
1996, 911 Carrera 4S	7327-D609**	D/D	7326-D446**
<u>SUBARU</u>			
1996, Impreza	7442-D563**	D/N	1462-S676*
OR	7350-D470**	D/D	7351-D471**
1996, Legacy	7350-D470**	D/N	1462-S676*
OR		/D	7351-D471**
1996, SVX	7433-D554**	D/D	7351-D471**

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>SUZUKI</u>			
1996, Esteem	7557-D677**	D/N	1461-S630*
1996, Sidekick 2DR		/N	1491-S710*
1996, Sidekick 4DR	7435-D556**	D/N	1492-S711*
	OR 7559-D680**	D/	
	(Notes #1 & #14)		
1996, X90		/N	1491-S710*
<u>TOYOTA (See Comments & Corrections)</u>			
1996, Celica		/D	7562-D685**
			(Notes #4 & #18)
1996-95, Previa		/N	1358-S709*
			(Note #27)
1996, T100 4WD	7485-D686**	D/N	1397-589*
	(Note #19)		
1996, T100 1/2 Ton 2WD	7485-D686**	D/N	1397-589*
<u>VOLKSWAGEN (See Comments)</u>			
1996, Golf GTI	7434-D687**	D/D	7234-D340**
	(Note #20)		
1996, Eurovan	7516-D638**	D/N	1453-S666
	OR 7461-D581**	D/	
<u>VOLVO</u>			
1996, 850	7494-D618**	D/D	736-D31**
1996, 940	7512-D634**	D/D	7279-D391**
	OR	/D	7422-D541**
1996, 960	7512-D634**	D/D	7422-D541**

C O M M E N T SExisting lining used with new shoe:

<u>Lining</u>	<u>Assembly</u>	<u>Application</u>
1358	1358-S709	1996-95 Toyota Previa Rear
7427	7427-D683	1995 BMW 740i, 740iL & 750iL Rear
7434	7434-D687	1996 Volkswagen Golf GTI Front
7485	7485-D686	1996 Toyota T100 4x2, 4x4 1/2T Front

Existing shoe with new lining:

<u>Shoe</u>	<u>Assembly</u>	<u>Application</u>
S697	1493-S697	1996 KIA Sephia Rear

C O R R E C T I O N S

Catalog lists FMSI 1358-505 as rear on 1995 Toyota Previa. The correct listing is FMSI 1358-S709.

1995 BMW 740i & 740iL front shown in catalog as FMSI 7426-D547. The correct listing is FMSI 7560-D681.

1995 BMW 750iL front was cataloged as FMSI 7284-D394. The correct listing is FMSI 7561-D682.

C O R R E C T I O N S (con't)

Catalog lists 1995 BMW 740i and 740iL rear as FMSI 7427-D548 and 1995 BMW 750iL rear as FMSI 7286-D396. The correct listing is FMSI 7427-D683.

Catalog shows 1995-94 BMW 318i, 325i, rear as FMSI 7286-D396. The correct listing is FMSI 7567-D692.

DISC BRAKE LINING ASSIGNMENTS

Note #1	<u>FMSI 7559</u>	7559-D680
	50.2 x 14.3 x 100.3	4 IM
	(1.98 x .563 x 3.95)	
Note #2	<u>FMSI 7560</u>	7560-D681
	55.9 x 18.3 x 98.3	4 IM
	(2.20 x .720 x 3.87)	
Note #3	<u>FMSI 7561</u>	7561-D682
	55.9 x 19.7 x 147.8	4 IM
	(2.20 x .776 x 5.82)	
Note #4	<u>FMSI 7562</u>	7562-D685
	33.0 x 15.5 x 80.5	4 IM
	(1.30 x .610 x 3.17)	
Note #5	<u>FMSI 7563</u>	7563-D688
	36.8 x 16.3 x 104.1	4 IM
	(1.45 x .642 x 4.10)	
Note #6	<u>FMSI 7564</u>	7564-D689
	67.1 x 17.8 x 96.3	4 IM
	(2.64 x .701 x 3.79)	
Note #7	<u>FMSI 7565A</u>	7565A-D690
	40.3 x 10.8 x 125.3	- 20
	(1.59 x .425 x 4.93)	
Note #8	<u>FMSI 7566</u>	7566-D691
	55.1 x 16.4 x 131.8	4 IM
	(2.17 x .646 x 5.19)	
Note #9	<u>FMSI 7567</u>	7567-D692
	27.9 x 16.1 x 78.0	4 IM
	(1.10 x .634 x 3.07)	
Note #10	<u>FMSI 7568</u>	7568-D693
	26.4 x 14.7 x 59.7	4 IM
	(1.04 x .579 x 2.35)	

DRUM BRAKE LINING ASSIGNMENTS

Note #11	<u>FMSI 1491</u> 220.0dd - 33.8 x 4.4 x 208.3 (8.66 - 1.33 x .173 x 8.20)	1491-S710 4 Bonded
Note #12	<u>FMSI 1492</u> 254.0dd - 44.7 x 4.3 x 241.0 (10.00 - 1.76 x .170 x 9.49)	1492-S711 4 Bonded
Note #13	<u>FMSI 1493</u> 200.0dd - 35.0 x 4.7 x 191.5 (7.87 - 1.38 x .185 x 7.54)	1493-S697 4 Bonded

DISC BRAKE SHOE ASSIGNMENTS

Note #14	<u>FMS D680</u> 110.0 x 5.0 (4.33 x .197)	7559-D680	Suzuki
Note #15	<u>FMS D681</u> 156.5 x 5.6 (6.16 x .220)	7560-D681	BMW
Note #16	<u>FMS D682</u> 165.1 x 5.9 (6.50 x .232)	7561-D682	BMW
Note #17	<u>FMS D683</u> 123.2 x 5.1 (4.85 x .201)	7427-D683	BMW
Note #	<u>FMS D684</u> - Will be released next Bulletin		
Note #18	<u>FMS D685</u> 107.5 x 5.6 (4.23 x .221)	7562-D685	Toyota
Note #19	<u>FMS D686</u> 132.8 x 5.5 (5.23 x .217)	7485-D686	Toyota
Note #20	<u>FMS D687</u> 156.5 x 5.6 156.5 x 5.6 (6.16 x .220) (6.16 x .220)	7434-D687	Volkswagen
Note #21	<u>FMS D688</u> 140.2 x 5.6 140.2 x 5.6 (5.52 x .220) (5.52 x .220)	7563-D688	Jaguar
Note #22	<u>FMS D689</u> 97.8 x 4.6 (3.85 x .181)	7564-D689	Mercedes

DISC BRAKE SHOE ASSIGNMENTS (con't)

Note #23	<u>FMS D690</u> 140.5 x 4.8 (5.53 x .189)	7565A-D690	Ford Mercury
Note #24	<u>FMS D691</u> 158.8 x 5.5 (6.25 x .217)	7566-D691	Nissan
Note #25	<u>FMS D692</u> 123.2 x 5.2 (4.85 x .205)	7567-D692	BMW
Note #26	<u>FMS D693</u> 61.7 x 4.6 (2.43 x .181)	7568-D693	KIA

DRUM BRAKE SHOE ASSIGNMENTS

Note #27	<u>FMS S709</u> 254.0 x 50.0 (10.00 x 1.97)	1358-S709	Toyota
Note #28	<u>FMS S710</u> 220.0 x 34.0 (8.66 x 1.34)	1491-S710	GEO Suzuki
Note #29	<u>FMS S711</u> 254.0 x 45.0 (10.00 x 1.76)	1492-S711	GEO Suzuki

The data shown in this bulletin has been supplied by sources considered to be reliable. While we believe that such information is correct, the Institute cannot and does not accept any responsibility or liability for errors or omissions, or harm resulting therefrom.

The data shown in this bulletin indicates dimensions only and in no way refers to quality of any materials that may be embodied in the product or particular application involved, and moreover, SINCE FIELD CONDITIONS AND OTHER FACTS MAY NECESSARILY VARY FROM ONE APPLICATION TO ANOTHER, FRICTION MATERIALS SUPPLIERS AND INSTALLERS SHOULD RELY ULTIMATELY AND SOLELY UPON THEIR OWN EXPERTISE AND JUDGMENT AS TO QUALITY AND DIMENSIONAL SIZE. Under no circumstances should replacement items be used when they do not appear to fit, nor be "forced" to fit, nor be modified in the field instead of obtaining a proper sized item from a supplier. If such items are modified in the field to fit, the Institute specifically disclaims all liability and responsibility for any harm resulting therefrom.

If any error or omission is noted in this bulletin, it should be reported immediately to the Friction Materials Standards Institute, Inc., 588 Monroe Turnpike, Monroe, Connecticut 06468.