

CENTRAL CRAFTS
CONTROL OF ASBESTOS DUST

File - Hecht

1. Approved respirator shall be worn (M.S.A. Comfo II with GMA cartridges and Type "F" filters) (3M #8710 disposable).
2. Disposable type coveralls, head and foot covers are to be worn over Plant work clothing.
3. Dampen materials prior to and during removal.
4. Remove hangers, supports, and outer covering carefully. Do not let material drop and create dust.
5. Avoid sawing where possible. Knife cutting is preferred.
6. Avoid dry sweeping, keep products in wet state. When possible use approved vacuum cleaner.
7. Designate work area as "Limited Access" Call Central Crafts I.H.S. coordinator for contact code number. Rope off area, display proper asbestos caution sign, place sign in/out log sheet on job site, record time exposure in limited access area. Return sign in/out log sheets to Central Crafts I.H.S. Coordinator.
8. Maintain good housekeeping.
9. Place waste materials and disposable clothing in impermeable bags.
10. Label or tag impermeable bags with warning tags, transport to Plant disposable area.

SAMPLE TAG: YELLOW AND BLACK

CAUTION

CONTAINS ASBESTOS

AVOID OPENING OR BREAKING CONTAINER

BREATHING ASBESTOS IS HAZARDOUS TO YOUR HEALTH

RD/sch
8-29-79


578

EXHIBIT # Depont #20
DATE Dec 5 1983
MASTROIANNI & FORMARO
ATTORNEYS AT LAW

L-13011-17-23
☒ FOR IDENT ☐ IN EVIDENCE
JUN 25 1981

JOSEPH J. HECHT

DUP 0905448



121379

SC-DP-05995