

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	12/16/2024	Time	09:00	
		Operator Representative CapturePoint, LLC				
Operator Info	CapturePoint, LLC	Inventory ID OS3865000				
	1101 Central Expwy S.,	API Well No				
	Suite 150	Lease Name NBU				
	Allen, TX 75013	Well ID 102 W6				
	Phone: 832-300-8221					
Location	SW 06 26N 06E	Status	Inactive	Well Type	Enhanced Recovery	
Latitude	36.759562	Longitude	-96.703548			
Inspection Reason	Responsible Company at		CapturePoint, LLC			
		Time of Inspection				
Inspect No.		Date Last MIT	06/09/2021	Last Test Result	Fail	
Casing	4.5	Tubing		USDW		
Monitoring Device Elected Monitoring Device FLM Canister Pressure Lease Status Barrel Monitor Hooked Up? Barrel Fluid Level (%) Flowline Hooked Up? Injecting	N	Tubings	Annulus	AUTHORIZED		
		Fittings	N	N	Max Pressure	764
		Actual Pressure		Max Volume		
		Determined?		Max Inj Units	Barrels Per Month	
		Static Fluid Level				
		Determined?				
		Injection Rate (bpd)				
Inspection Comments		CapturePoint, LLC cut the well tubing at 275 feet below the surface. Inspector observed Hurricane Services Inc (HSI) run in well OS3865000 and tag the top of the middle plug at 275 feet. HSI pumped 50 sacks of cement from 275 to surface. Inspector observed cement standing full at the surface.				
Inspector Signature						
Supervisor Signature						

Appendix 1

Photograph Log 1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.759562, -96.703548		
City: Shidler	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010559

Orientation: N/A

Date of Photo: 12/16/2024

Time of Photo: 10:41 AM

Latitude: 36.759652

Longitude: -96.703548

Photographer: Matthew Allen

Description: This was well OS3865000 with cement standing at the surface.