

Granite State Concrete Co. Inc


January 25, 2023

Inspector: Solanch Pastrana-Del Valle

Permit writer: Sharon DeMeo

ECAD Intern: Jeremy Rolfe







Quarry



Quarry






Quarry water flows through here to Gilson Brook Pond



Quarry water flows through here to Gilson Brook Pond



Quarry water flows through here to Gilson Brook Pond













Shed on open area next to Gilson Brook Pond



NPDES Outfall 001









Water intake from Gilson Brook Pond for Truck Water








Inside pump house



Inside pump house




Inside pump house



Inside pump house





Unknown pipe from pump house



Standing water near stone crushing operations




Standing water near stone crushing operations




Standing water near stone crushing operations

Non-potable water tank






Stone crushing operations



Stone crushing operations



Stone crushing operations



Stone crushing operations



Stone crushing operations



Water truck






Operations south of the facility



Water flows to stormwater outfall 001 thru wetland (see next slide)



Water flows to stormwater outfall 001



Stormwater outfall 001 to Gilson Brook Pond



Culvert with running water from unknown source












Wash-out pits




Washout pits














Propane tank



















Thawed section of Gilson Brook (behind washout pits)





