






Attachment 7



	SIFEL	KJC-1801AB	KJC-1802AB
Appearance after sulfur test			
Penetration	35	25	55
Moisture permeation (g/m ² ·day)	7	~100	~100



Elastomer delamination and broken wires after decompression test using non fluoroelastomers



Catastrophic status of elastomer after soapy water exposure in comparison with robust fluoroelastomer