

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date:	3/11/2026	
Media Program:	Water, Clean Water Act (Brine)	
Regulatory Program:	Brine (NPDES)	
Company Name:	CapturePoint, LLC	
Facility Name:	North Burbank Unit (NBU) 24 Battery	
Facility Physical Location:	36.830275, -96.712404	
(city, state, zip code)	Webb City, Oklahoma, 74652	
Mailing address:	1833 S. Morgan Road	
(city, state, zip code)	Oklahoma City, Oklahoma, 73128	
County/Parish:	Osage	
Facility Phone Number:	918-287-6811	
Facility Contact:	Talia Clark	HSE Tech
FRS Number:	n/a	
Identification/Permit Number:	OKU002197	
Media Identifier Number:	n/a	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Matthew Allen	EPA/Region 6 ECDW	Inspector
EPA Lead Inspector Signature/Date		
	Matthew Allen	Date
Supervisor Signature/Date		
	Jeanne Eckhart	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

Environmental Protection Agency (EPA) Region 6 inspector Matthew Allen arrived at the CapturePoint, LLC / North Burbank Unit (NBU) 24 Battery (EPA ID No. OKU002197) at 12:40PM on 3/11/2026 for an announced inspection. This was a follow-up inspection to an inspection conducted by EPA on 2/5/2026 in response to a National Response Center Spill Report (NRC No. 1454114) received by EPA Region 6. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with EPA regulations. There were no other federal, state, or local agency representatives present at the time of the inspection.

FACILITY DESCRIPTION

EPA conducted an inspection at the CapturePoint, LLC / North Burbank Unit 24 Battery, where a 4" production line connected to the NBU 24 battery failed and released a company-estimated 50 barrels of saltwater and 7 barrels of oil to the land surface. The spilled fluids flowed west approximately 50 feet and discharge into an unnamed tributary of Hay Creek.

Section II – OBSERVATIONS

I observed the release point of the spill which was a 4" steel flowline. At the time of the inspection, CapturePoint, LLC had repaired and returned the line to service, see photo No. 1, Appendix 1 (Photo Log). For additional GPS location information and photo metadata, see the attached photo log.

I observed the point of entry (POE) into the unnamed tributary of Hay Creek. At the same location, I observed a TDS field reading of 553 mg/L, which represented a return to "background" TDS levels for the area. See photo No. 2 and No. 3.

I observed the unnamed tributary from the POE to the lowermost containment dam, approximately 500 feet. I observed no remaining spill impacts along the unnamed tributary.

At the lowermost containment dam, which was also the end of observed spill impacts, I observed a TDS field reading of 546 mg/L on the upstream side of the dam. This TDS field reading represented a return to pre-spill or "background" TDS levels. See photo No. 4 and No. 5.

All TDS field readings observed throughout the inspection were taken with a properly calibrated, EPA issued, YSI Pro 30 conductivity meter.

Section III – AREAS OF CONCERN

There were no areas of concern at the time of the inspection.

Section IV – FOLLOW UP

There is no follow-up required. CapturePoint, LLC remediated the unnamed tributary to "background" TDS levels.

Section V – LIST OF APPENDICES

Appendix 1 – Photo Log – 5 photos taken on 3/11/2026

Appendix 1

Photograph Log

5 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.830275, -96.712404		
City: Webb City	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010792

Orientation: SSW

Date of Photo: 3/11/2026

Time of Photo: 12:40 PM

Latitude: 36.830275

Longitude: -96.712404

Photographer: Matthew Allen

Description: This photo shows the release point of the spill and shows a flowline that CapturePoint, LLC repaired and returned to service.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.830275, -96.712404		
City: Webb City	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010793

Orientation: N/A

Date of Photo: 3/11/2026

Time of Photo: 12:41 PM

Latitude: 36.830041

Longitude: -96.712362

Photographer: Matthew Allen

Description: This photo shows a TDS field reading of 553 mg/L observed at the point of entry into the unnamed tributary of Hay Creek. This reading was consistent with “background” TDS levels in the area.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 3

Location: 36.830275, -96.712404		
City: Webb City	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010794

Orientation: SW

Date of Photo: 3/11/2026

Time of Photo: 12:41 PM

Latitude: 36.830041

Longitude: -96.712362

Photographer: Matthew Allen

Description: This photo shows the location of the TDS field reading from photo No. 2.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 4

Location: 36.830275, -96.712404		
City: Webb City	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010795

Orientation: N/A

Date of Photo: 3/11/2026

Time of Photo: 12:45 AM

Latitude: 36.829301

Longitude: -96.711315

Photographer: Matthew Allen

Description: This photo shows a TDS field reading of 546 mg/L observed on the upstream side (impacted side) of the lowermost containment dam constructed during cleanup operations. This TDS reading was consistent with "background" TDS levels for the area.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 5

Location: 36.830275, -96.712404		
City: Webb City	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010797

Orientation: WNW

Date of Photo: 3/11/2026

Time of Photo: 12:45 AM

Latitude: 36.829297

Longitude: -96.711337

Photographer: Matthew Allen

Description: This photo shows the location of the TDS field reading from photo No. 4.