



**Region 6 Compliance Assurance and Enforcement Division
INSPECTION REPORT**

Inspection Date(s):	10/19/2017		
Media:	Water		
Regulatory Program(s)	NPDES		
Company Name:			
Facility Name:	[REDACTED]		
Facility Physical Location:	[REDACTED]		
(city, state, zip code)	Kentwood, LA 70444		
Mailing address:	[REDACTED]		
(city, state, zip code)	Kentwood, LA 70444		
County/Parish:	Tangipahoa		
Facility Contact:	[REDACTED]	Owner	
FRS Number:	N/A		
Identification/Permit Number:	LAU000479		
Media Number:	N/A		
NAICS:	0241		
SIC:	112120		
Personnel participating in inspection:			
[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
Collin Martin	6EN-WC	Inspector	214-665-8380
Eura Dehart	LDEQ	Inspector	285-219-3030
EPA Lead Inspector Signature/Date	COLLIN MARTIN Digitally signed by COLLIN MARTIN DN: c=US, o=U.S. Government, ou=USEPA, ou=Staff, cn=COLLIN MARTIN, dnQualifier=0000082180 Date: 2017.12.07 11:34:00 -06'00'		
	{Inspector name}		Date
Supervisor Signature/Date	 {Supervisor name}		12/7/17
	{Supervisor name}		Date

[REDACTED]
Inspection Date: 10/19/2017**Section I – INTRODUCTION****PURPOSE OF THE INSPECTION**

EPA Region 6 inspector Collin Martin and LDEQ inspector Eura Dehart arrived at [REDACTED] at 9:49 A.M. on 10/19/2017 for an unannounced inspection. We met with [REDACTED] at the Opening Conference. I presented my credentials to [REDACTED] and informed him that this was an EPA inspection to determine facility compliance with the Clean Water Act. The scope of the inspection is a Compliance Evaluation Inspection.

FACILITY DESCRIPTION

[REDACTED] is an unpermitted facility that has approximately 85 cattle. At the time of the inspection, according to [REDACTED], the facility was milking 65 cows. In addition to the milking cows, [REDACTED] notified us that there were approximately 10 head of dry cows, 10 calves. The cows are milked twice per day and between sessions kept in pasture.

Section II – OBSERVATIONSCoordination with NRCS:

[REDACTED] informed us that he is under contract with NRCS for a new dewatering pump, an agitator, a reel gun for land application, and a lagoon cleanout.

Retention Control Structure (RCS):

At the time of the inspection, [REDACTED] had one RCS. According to [REDACTED], this RCS was approximately twenty years old and was last cleaned out around five years ago. We observed the RCS to be in good condition and observed no evidence of discharge.

Land Application Areas:

[REDACTED] informed us that he has approximately six acres to which he could land apply his wastewater liquids and solids. [REDACTED] noted that once NRCS installed his new irrigation system, he would be able to apply to approximately sixty acres.

Dewatering Equipment:

At the time of the inspection, [REDACTED] had one small pump available for dewatering the lagoon. [REDACTED] informed us that he utilizes the pump whenever he notices the wastewater approaching the crest of the RCS berm.

Mortality Management Area:

[REDACTED] did not have a dedicated mortality management area as [REDACTED] buries his mortalities where they fall.

██████████
Inspection Date: 10/19/2017

Commodities Storage:

At the time of the inspection, ██████████ stored his feed in bins and his hay in a barn.

Section III – AREAS OF CONCERN

We observed no areas of concern at the time of our inspection.

Section IV – LIST OF APPENDICES

Appendix 1 – Photo Log – 2 photos taken 10/19/17

Appendix 1

Photograph Log



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: [REDACTED]		
City: Kentwood	County/Parish: Tangipahoa	State: Louisiana



Photo File Name: DSCN6112.JPG

Date of Photo: 10/19/2017

Time of Photo: 10:08 A.M.

Photographer: Collin Martin

Description: Photo Taken facing east across RCS.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: [REDACTED]		
City: Kentwood	County/Parish: Tangipahoa	State: Louisiana



Photo File Name: DSCN6115.JPG

Date of Photo: 10/19/2017

Time of Photo: 10:13 A.M.

Photographer: Collin Martin

Description: Phot taken facing north towards dewatering pump.