

"NORWOOD"

BRAND

TO DUPLICATE THIS FOLDER ORDER

Globe-Wernicke

NO. 81¹/₅

MADE IN U. S. A.

KE 0013241

in this plant, the following specific recommendations are made:

1. Installation of a properly designed exhaust ventilation system in the mixing room of Building 4.
2. Requirement that men working in dusty freight cars wear dust respirators.

With regard to the first of these, it is important, if sole dependence is placed upon the ventilation system, that hoods be properly placed relative to mixers and that hood entrance velocities be such as to insure collection of all highly concentrated dusts given off by the operation of charging the mixers. The appended blueprint shows location of sampling points in the mixing room and analyses of the corresponding samples. A careful study of these data should give some idea as to the parts of the room where ventilation is most needed. It seems advisable to locate hoods near each mixer in such a way that all dust generated by charging mixers would be drawn into the system and away from the operators. If it proves to be impractical to do this for all mixers, it definitely should be done for all those in which lead or silica paints are mixed and those paints should never be mixed in other machines.

In addition to hoods located near the mixers, there should be exhaust ventilators located in all parts of the room where dry dusts are stored and handled. Two such places are indicated on the drawing by samples number 28 and number 4. It may be stated in

saintaining low dust concentrations in the surrounding air.

There is considerable difference between conditions in the plant as a whole in summer and those in winter. A comparison of samples taken in summer (July) with those taken in winter is tabulated in Table I, taking average results of all samples taken in the mixing room at each time except that samples taken near mixers during operation of charging are omitted.

TABLE I

Comparison of Average Dust Samples Taken in Mixing Room

	Summer	Winter	% Increase
Dust Concentration, particles per cu. ft.	1,283,500	6,729,800	424
Lead Concentration, mg. per 10 cu. M.	0.193	0.832	356

These data are easily accounted for by observation of ventilation conditions during the two extreme seasons of the year. In summer the plant is operated with most windows open and natural ventilation gives rapid changes of air within the plant. In winter the windows are all closed and with a change of air occurring very seldom, concentrations of dust and other contaminants continually increase throughout the working day. This is particularly true of the most minute particles which remain in suspension indefinitely, instead of settling out as do the larger particles. Since these

Sample No.	Location	Operation	Dust Count Particles/cu.ft.	Lead Conc. Mg./10 cu.M.
1	Mixing Room	Charging Mixer No. 6 for Paint No. 782, Mellow Gloss White	2,746,800	0.165
2	Mixing Room	Charging Mixers 1 and 3 for Paint No. 1003, High Stand- ard, Stock White	6,840,000	1.53
11	Receiving Department	Unloading freight car of Leaded Zinc Oxide	20,145,600	25.7
12	Receiving Department	Unloading freight car of Titanium Oxide	12,053,200	2.25

Table II shows analyses of four samples taken under unusual conditions. Samples 1 and 2 were taken near mixers during the charging operation in summer. The analyses show that the men engaged in these operations are subject to hazardous concentrations of dust for the short time required for charging the mixers. Continuous exposures to such concentrations would constitute a dangerous hazard. However, the chief significance of these data is that it indicates the principal origin of hygienic dust in the mixer room, namely the operation of charging the mixers with dry powdered materials.

Samples 11 and 12 were taken inside freight cars which were being emptied of leaded zinc oxide and titanium oxide respectively. Both doors of each car were open but neither was ventilated by any artificial method. The materials were contained in paper bags. The bags were moved by hand from the floors of the cars to skids upon

KE 0013344

such lead concentrations are met only in cars loaded with dusts whose lead content is very high. These do not occur often enough to have caused serious exposures of the men in the past.

Since it might be impractical to attempt to ventilate the cars in a way that would effectively eliminate the hazard, the use of respirators has been previously and is again recommended in the unloading of all freight cars containing powdered materials.

Table III contains results of analyses of all samples taken in the plant. Those which are indicative of particular hazards have been discussed above. In general, it may be stated that all those which show lead concentrations below 1.0 milligram per 10 cubic meters and dust counts of less than 1,500,000 particles per cubic foot indicate conditions that are safe from those hazards. The dust count of 2,105,000 shown for the grinding room is not a dangerous condition but is simply higher than normal due to poor winter ventilation in that part of the plant.

The analyses of dust scrapings from the mixing room indicate that over a long period of time the lead content of atmospheric dusts in the mixing room is about 2.7% by weight. This was determined by analyzing for lead samples of the dust which has settled over such things as pipes near the ceiling and motor starter boxes on the walls.

room where no dust is generated to see if the permanent overall hazard as well as the local acute hazard have been removed.

RE 0013246

Summary of Data

Sample No.	Location	Date	Amount of Sample	Pb Found Mg.	Mg. Pb per 1000 Cu.ft.	Mg. Pb per 10 Cu.M.	Dust Count Millions of Particles per Cu. Ft.	% Pb by Weight
1	Mixing Room	7-23-40	15 cu.ft.	0.007	0.467	0.165	2.7468	
2	Mixing Room	7-23-40	30 cu.ft.	0.130	4.332	1.530	6.8400	
3	Mixing Room	7-23-40	53 cu.ft.	0.020	0.377	0.130	0.9508	
4	Mixing Room	7-23-40	60 cu.ft.	0.072	1.200	0.420	0.8132	
6	Roof Bldg. 4	7-23-40	33 cu.ft.	0.004	0.121	0.043	0.3032	
7	Maintenance	7-23-40	45 cu.ft.	0.014	0.311	0.110	1.2800	
8	Mixing Room	7-23-40	48 cu.ft.	0.020	0.416	0.150	2.6500	
9	Mixing Room	7-23-40	30 cu.ft.	0.006	0.200	0.071	0.7200	
10	Bldg. 3, Base't.	7-24-40	60 cu.ft.	0.004	0.067	0.023	0.5068	
11	Freight Car	7-24-40	33 cu.ft.	2.400	72.727	25.700	20.1456	
12	Freight Car	7-24-40	30 cu.ft.	0.190	6.333	2.250	12.0532	
13	Mixing Room	7-23-40	0.419 gm.	6.500				1.56
14	Mixing Room	7-23-40	1.3445 gm.	60.000				4.47
15	Mixing Room	7-23-40	1.741 gm.	36.000				2.07
16	Mixing Room	7-23-40	1.638 gm.	28.000				1.65
17	Mixing Room	7-23-40	0.271 gm.	10.000				3.70
24	Mixing Room	12-11-40	32.5 cu.ft.	0.165	5.077	1.79	8.7140	

TABLE III continued

Sample No.	Location	Date	Amount of Sample	Pb Found Mg.	Mg. Pb per 1000 Cu.Ft.	Mg. Pb per 10 Cu.Ft.	Dust Count Millions of Particles per Cu. Ft.	% Pb by weight
25	Mixing Room	12-11-40	48.75 cu.ft.	0.052	1.065	0.40	5.0340	
26	Mixing Room	12-11-40	48.75 cu.ft.	0.082	1.682	0.63	6.1780	
27	Mixing Room	12-11-40	48.75 cu.ft.	0.020	0.411	0.15	3.2250	
28	Mixing Room	12-11-40	32.5 cu.ft.	0.130	4.000	1.44	10.4980	
30	Grinding Room	12-11-40	32.5 cu.ft.	0.010	0.308	0.11	2.1050	
31	Test Room	12-11-40	65.0 cu.ft.	0.072	1.107	0.39	1.1940	

DUST SAMPLES

Lowe Brothers Company - Dayton, Ohio

Analysis Number	Description	Liter Volume Air	Mg Pb Pound	Mgs Pb/ 10 Cu M.
40C-24	Mixing Room, Bldg. 4, West Center of room	920	0.165	1.79
40C-25	Mixing Room, Bldg. 4, Southwest Corner	1300	0.052	0.40
40C-26	Mixing Room, Bldg. 4, South Center of room	1300	0.082	0.63
40C-27	Mixing Room, Bldg. 4, Southeast Corner of room	1300	0.020	0.15
40C-28	Mixing Room, Bldg. 4, Northeast Corner of room	920	0.130	1.44
40C-29	Mixing Room, Bldg. 4, Northwest Corner of room	920	0.190	2.11
40C-30	West End of Grinding Room -- near Roll Mill	920	0.010	0.11
40C-31	Test Room on West End of Sixth Floor	1840	0.072	0.39

Samples Received: 12-12-40

Samples Reported: 1-14-41

RE 0013255

Air and Dust Samples from Plant of Lowe Brothers Company, Dayton, Ohio

Analysis Number	Description	Gms or Volume	Mgs Pb Found	% Pb	Pb/10 Cu.H	Other %	Remarks
40C-1	Air - Mixing room - Bldg. 4, 5th floor, near mixer 6, 10:08 - 10:13 a.m. Paint #782	425 L	0.007		0.165	Si +++	Paint #782 = Lithopone 92.8%, PbO_2 7.2%. Lithopone = 70% $BaSO_4$, 30% ZnS .
40C-2	Air - Mixing room - Bldg. 4, 5th floor, near mixers 1 and 3, 10:23 - 10:33 a.m. Paint #1003	849 L	0.13		1.53	Si +++	Paint #1003 = leaded zinc 40%, PbO_2 20%, Mayox 6%, Asbestine 34% Mayox = 95% PbO_2 (impurities, Ca and Ba sulphates). Asbestine = silicious fibrous particles
40C-3	Air - Mixing room - Bldg. 4, 5th floor, N.W. corner of mixing room, nearest mixers idle, 10:52 - 11:10 a.m.	1500 L	0.02		0.13		
40C-4	Air - Mixing room - Bldg. 4, 5th floor, center of mixer room near open barrels of pigment, 12:32 - 12:52 p.m.	1698 L	0.072		0.42		
40C-5	Same as 40C-4 except taken in chrome-plated sampling tube, 12:59 - 1:19 p.m.	1698 L	0.06		0.35		
40C-6	Air - roof Bldg. 4 (Control Sample) 1:41 - 1:52 p.m.	934 L	0.004		0.043		
40C-7	Air - Maintenance Dept. - near stone dressing operation (local exhaust hood) 1:59 - 2:14 p.m.	1274 L	0.014		0.11		

ME 0013357

Analysis Number	Description	Gms or Volume	Mgs Pb Found	% Pb	Pb/10 Cu.M	Other %	Remarks
400-13	Dust - Mixing room, Bldg. 4, 5th floor, from pipe near ceiling 6 feet from freight elevator	0.419 gm	6.50	1.56		Approx. 5% SiO ₂	
400-14	Dust - same as 400-13, from floor in S.W. corner	1.34 gm	60.00	4.47			
400-15	Dust - same as 400-13, from motor starter box for mixers 7, 8, and 9, East wall	1.74 gm	36.0	2.07			
400-16	Dust - same as 400-13, from motor starter box on opposite wall (west)	1.70 gm	28.0	1.65			
400-17	Dust - same as 400-13, from motor starter box on north wall 30 feet from washroom door	0.27 gm	10.0	3.70			

Received: 7-23-40

Reported: 9-15-40

KE 0013258