

Date of Inspection: March 1999 Quarter of Inspection: First Quarter

VCM BLEEDER VALVE INSPECTION

Area / Location	P&ID #	Description	Bleeder Valve / Plug #	Comments	Checked and Corrected
OM	90113	PP-112 Outlet Line	5 BV	Plug Needed	JDY
OM	90114	FL-050, 051 Outlet Line	19 BV	Loose Plug	JDY
OM	90114	Underside of DM-703	12 BV	Illegal Hose Connection	JDY
OM	90114	Underside of DM-702	3 BV	Plug Needed	JDY
NM	90109	EX-335 Inlet	22BV	Plug Needed	JDY
NM	90110	Recovery Compressor CP-905	9 P	Loose Plug	JDY
NM	90111	FL-732	13 BV	Loose Plug	JDY
NM	90111	FL-731	10 BV	Loose Plug	JDY
NM	90111	EX-334 Inlet Line	3 BV	Plug Needed	JDY
NM	90111	EX-334	1 BV	Loose Plug	JDY
NM	90112	EX-338	2 P	Plug Needed	JDY
NM	90115	PP-184 South	12 BV	Plug Needed	JDY
NM	90115	PP-185 North	20 BV	Plug Needed	JDY
NM	90115	FL-386	18, 19 BV	Water Hose Attachments	JDY
NM	90135	Underside of DM-076	7 BV	Plug Needed	JDY
NM	90139	FL 013, 012 Inlet	5 BV	Plug Needed	JDY
NM	90139	PP-502 Inlet	3 BV	Cover Needs Fastening	JDY
NM	90141	PP-509 Inlet	11 BV	Cover Needs Fastening	JDY
NM	90142	EX-010 Inlet	1 BV	Plug Needed	JDY

Note: All other bleeder valves and plugs were inspected and found in satisfactory condition.

NM - New Module
OM - Old Module
VS - Sphere
DY - Incinerators