

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	11/07/2019	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	Weiser-Brown Operating Company	
Facility Name:	Bodcaw Kilpatrick Unit	
Facility Physical Location:	33.536028, -93.389768	
(city, state, zip code)	Bodcaw, Arkansas 71858	
Mailing address:	117 E. Calhoun	
(city, state, zip code)	Magnolia, Arkansas 71753	
County/Parish:	Nevada County	
Facility Phone Number	870-234-3050	
Facility Contact:	Chris Weiser	
	chrisw@weiser-brown.com	
FRS Number:	N/A	
Identification/Permit Number:	N/A	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		12 DEC 2019
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Weiser-Brown Operating Company oil and gas facility located at latitude 33.536028 and longitude -93.389768 near Bodcaw, Arkansas on 11/07/2019 for an unannounced inspection. There were no representatives of Weiser-Brown Operating Company present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This facility is known as the Bodcaw Kilpatrick Unit tank battery and is located in the Bodcaw field.

Section II - OBSERVATIONS

The facility had low berms on the secondary containment of the tank battery. I observed that the oil storage tanks were seeping oil during the inspection. I observed that the drain valve on berm built around the separator was open during the inspection. I observe a hose used for siphoning was on the berm built around the salt water storage tank.

Section III – AREAS OF CONCERN

The facility had inadequate secondary containment, including an open drain valve. And there was oil leaking from the storage tank.

Section IV – FOLLOW UP

EPA water enforcement will refer this facility to EPA SPCC program and conduct a follow up inspection in approximately 6 months.

Section V – LIST OF APPENDICES

N/A