

INSPECTION REPORT

Inspection Date(s):	April 10, 2015		
Media:	CWA 311 SPCC		
Regulatory Program(s)	Underground Injection Control - Brine		
Company Name:	J & B Oil LLC		
Facility Name:	TC Patton Lease		
Facility Physical Location:	NW/4 Section 32-T15S-R16W		
(city, state, zip code)	Smackover, AR		
Mailing Address:	812 Elm Street		
(city, state, zip code)	Smackover, AR 71762		
County/Parish:	Ouachita County		
Facility Contact	N/A	N/A	
	N/A		
FRS Number:	N/A		
Identification/Permit Number:	N/A		
Media Number:	N/A		
NAICS:	21111		
SIC:	1311		
Personnel participating in the inspection:			
Kent Sanborn	6EN-WR	EPA Inspector	918-557-1615
N/A	N/A	N/A	N/A
N/A	N/A	N/A	N/A
N/A	N/A	N/A	N/A
N/A	N/A	N/A	N/A
N/A	N/A	N/A	N/A
N/A	N/A	N/A	N/A
N/A	N/A	N/A	N/A
N/A	N/A	N/A	N/A
N/A	N/A	N/A	N/A
N/A	N/A	N/A	N/A
N/A	N/A	N/A	N/A
EPA Lead Inspector Signature/Date	Kent Sanborn Digitally signed by Kent Sanborn DN: cn=Kent Sanborn, o=EPA, ou, email=sanborn.kent@epa.gov, c=US Date: 2015.05.26 13:11:55 -05'00'		
	Kent Sanborn		Date
Supervisor Signature/Date	WILLIE LANE Digitally signed by WILLIE LANE DN: c=US, o=U.S. Government, ou=USEPA, ou=Staff, cn=WILLIE LANE, dnQualifier=000007235 Date: 2015.06.09 16:03:00 -05'00'		
	Willie Lane Jr., Chief, Water Resources Section(6EN-WR)		Date

Section I - INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector Kent Sanborn visited the J &B Oil LLC oil production facility located in the NW/4 Section 32-T15S-R16W near Smackover, Arkansas on April 10, 2015. No representative of J &B Oil LLC was present for the inspection. The inspection was conducted by authority of the Clean Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

Known as the TC Patton lease. There is 1-gun barrel separator, 1-200 barrel brine tank, a horizontal separator, and 1-200 barrel stock tank.

Section II - OBSERVATIONS

There is an electric pump set up to drain the pit. The pump is not on. Three inches of rain last night. Some grading on prior damage south of the battery toward the creek.

Section III - AREAS OF CONCERN

Pit is getting full.

Section IV - FOLLOW UP

Re-inspect in a few months.

Section V - LIST OF APPENDICES

There are no attachments to this report.