

Appendix B Photograph Log



Photograph 1. View, facing east, of the Facility's office building from the entrance at South 3rd Street.



Photograph 2. View, facing east, of the Facility's entrance from West Brighton Avenue.



Photograph 3. View, facing southeast, of the Facility's machine to process materials.



Photograph 4. View, facing east, of the Facility's machine to process materials and materials storage.



Photograph 5. View, facing northeast, of materials at the Facility which appear to have been compacted and bound.



Photograph 6. View, facing east, of recyclable materials stored at the Facility.



Photograph 7. View, facing east, of recyclable materials stored at the Facility.



Photograph 8. View, facing southwest, of waste containers in the northwest corner of the Facility.



Photograph 9. View, facing south, of the Facility's impervious surface.