

Region 6 Compliance Assurance and Enforcement Division

INSPECTION REPORT

Inspection Date(s):	August 13, 2018		
Media:	SDWA Brine		
Regulatory Program(s)	Underground Injection Control - Brine		
Company Name:	Wachtman Schroeder Oil Company		
Facility Name:	Whitetail Stuart		
Facility Physical Location:	SE/4, Sec. 30, T , R		
(city, state, zip code)	Pawhuska, Oklahoma		
Mailing Address:	2400 McKenzie Rd.		
(city, state, zip code)	Pawhuska, OK 74056		
County/Parish:	Osage		
Facility Contact	N/A	N/A	
	N/A		
FRS Number:	N/A		
Identification/Permit Number:	OKU000872		
Media Number:	N/A		
NAICS:	21111		
SIC:	1311		
Facility Representatives:	Main Office	N/A	702-303-7954
	N/A	N/A	N/A
	N/A	N/A	N/A
	N/A	N/A	N/A
EPA Inspectors:	K.W. Sanborn	6EN-WR	918-557-1615
	N/A	N/A	N/A
	N/A	N/A	N/A
State Inspector(s):	N/A	N/A	N/A
	N/A	N/A	N/A
Other Inspector(s):	N/A	N/A	N/A
	N/A	N/A	N/A
EPA Lead Inspector Signature/Date			
	Kent Sanborn		Date
Supervisor Signature/Date for			
	Guy Tidmore		Date

Section I - INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Wachtman Schroeder Oil Company oil production facility located in the Latitude: 36.785178, Longitude: -96.268198 near Pawhuska, on August 13, 2018. No representative of Wachtman Schroeder Oil Company was present for the inspection. The inspection was conducted by authority of the Clean Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

The facility is known as the Whitetail Stuart Lease. I spoke with Mr. Wachtman about my concerns during the inspection.

Section II - OBSERVATIONS

With a calibrated YSI Pro 30 Conductivity Meter, I observed a Total Dissolved Solids (TDS) of 25,000 mg/L in the nearby creek at the previously identified point of entry from an inspection conducted on 08/02/2018. There was a temporary dam built downstream from the point of entry to prevent further pollutants from flowing downstream. I observed two truckloads of water being used to flush the creek area, and the flushing did not appear to reach the dam. I observed 7,000 mg/L TDS in the creek between the dam and the entry point.

Section III - AREAS OF CONCERN

The flow path and creek still have brine contamination occurring that continues to reach the creek.

Section IV - FOLLOW UP

Conduct a follow up inspection as needed.

Section V - LIST OF APPENDICES

There are no attachments to this report.