

HFC Import Inspection Worksheet

This worksheet is for inspection of Imported Hydrofluorocarbons (HFCs) subject to 40 CFR Part 84

Insp. No: 20230223-1022

Insp. Date: 2/23/2023

Inspector(s): ☒ E. Felix ☒ N. Dancher ☒ A. Isin ☒ J. Iatropulos

Start Time/Stop Time: Start 10:22am, End 11:30am

Location of Inspection

Facility Name: East Coast Warehouse

Address: 1150 Polaris Street, Elizabeth, NJ 07102

Facility Type: Customs and Border Protection (CBP) Warehouse

CBP POC Contact Information: Alexey Shalashov (alexey.shalashov@cbp.dhs.gov)

☒ Indicate here if entry was not filed at time of inspection

Importer Information (from Entry Documents)

☒ Indicate here if consignee is the same as importer

Importer Name: Mexichem Fluor Inc.

Importer Address: 4990B ICI Road, St. Gabriel, LA 70776

Importer No : 27-178566700

Consignee Name: Mexichem Fluor Inc.

Consignee Address: PO Box 30, St. Gabriel, LA 70776

POC Contact Information: sean.cunningham@mexichem.com

Visual Inspection HFC #1

Product Description: Zephex 134a

Chemical name/formula: 1,1,1,2-Tetrafluoroethane (HFC-134a)

Container Type: ☐ Service Can ☐ Ton Tank ☒ ISO Tank
☐ Refillable Cylinder ☐ Disposable Cylinder

Shipment/ Entry No: 916-48959616

Shipping Container No: SUTU-1044806

Arrival Date: 2/8/2023

Listed Qty: 1

Listed Mass: 20,000

Actual Mass:

Unable to weigh

☐ lb ☒ kg ☐ ton

Visual Inspection Notes:

Visual Inspection HFC #2

Product Description:

Chemical name/formula:

Container Type: ☐ Service Can ☐ Ton Tank ☐ ISO Tank
☐ Refillable Cylinder ☐ Disposable Cylinder

Shipment/ Entry No:

Shipping Container No:

Arrival Date:

Listed Qty:

Listed Mass:

Actual Mass: ☐ lb ☐ kg ☐ ton

Visual Inspection Notes:

Visual Inspection HFC #3

Product Description:

Chemical name/formula:

Container Type: ☐ Service Can ☐ Ton Tank ☐ ISO Tank
☐ Refillable Cylinder ☐ Disposable Cylinder

Shipment/ Entry No:

Shipping Container No:

Arrival Date:

Listed Qty:

Listed Mass:

Actual Mass: ☐ lb ☐ kg ☐ ton

Visual Inspection Notes:

Inspection Summary

Evidence/Samples taken and Description: N/A

Potential Follow-Up/Areas of Concern (e.g. potential deficiencies, actions taken by facility (if applicable)):

Inspection photo numbers: DSCN1045.jpg - DSCN1076.jpg (photographs taken by Cassidy Owen, EPA Contractor)

Camera Information: ☒ Nikon Coolpix WD300 ☐ Sony Olymos Other:

Photographer: ☐ E. Felix ☐ N. Dancher ☐ A. Isin ☐ J. Iatropulos

Lead Inspector Signature: AMELIE ISIN

Supervisor Signature: MARK PALERMO

Digitally signed by AMELIE ISIN
Date: 2023.04.11 13:37:00 -04'00'

Digitally signed by MARK PALERMO
Date: 2023.04.14 11:16:33 -04'00'

Guidance for Inspectors:

Inspector should obtain copies of the following when conducting inspections for CBP:

- Entry documents
- Invoice/Packing lists
- Bill of lading

Inspector should obtain the following key photographs:

- All sides of container to include any labels.