



## Photographs for Western Stone

Inspection Type: RI-Stormwater

---

Photo number 790 taken by **Privacy** on 11/15/2023.

Description:

Saw used in cutting rock. Located in the only building at top of site. When in use, water sprays from hose on left and collects in a trough along the building wall on the right hand side. Trough leads to settling tanks south of the building (see photos 792 & 793).



---

Photo number 791 taken by **Privacy** on 11/15/2023.

The direction of the photo is Northwest.

Description:

Fuel tank for on-site vehicles (red tank) sitting on top of storage shed. White piping on board frame is from the on-site well into the building and used to augment reuse water when the saw is in use.





## Photographs for Western Stone

Inspection Type: RI-Stormwater

---

Photo number 792 taken by **Privacy** on 11/15/2023.

The direction of the photo is Southwest.

Description:

Process water goes from trough inside the building, into one of three settling tanks located south of the building.



---

Photo number 793 taken by **Privacy** on 11/15/2023.

Description:

Settling tank showing pumping apparatus which pumps clean top water back to the saw for re-use.





## Photographs for Western Stone

Inspection Type: RI-Stormwater

---

Photo number 794 taken by **Privacy** on 11/15/2023.

The direction of the photo is Southeast.

Description:

Overview of some inventory on-site.



---

Photo number 795 taken by **Privacy** on 11/15/2023.

The direction of the photo is Northeast.

Description:

Main platform at facility with inventory stacked in various locations throughout site. Tractor with water tank and perforated PVC pipe used in summer months for dust control.





## Photographs for Western Stone

Inspection Type: RI-Stormwater

---

Photo number 796 taken by **Privacy** on 11/15/2023.

The direction of the photo is West.

Description:

Roadway with vegetated ditches.



---

Photo number 797 taken by **Privacy** on 11/15/2023.

The direction of the photo is West.

Description:

Some inventory in the northwestern part of the site.

