

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	08/11/2022	Time	10:00
Inspection Due	2021-09-19T00:00:00Z	Operator Representative	Calgary Energy, LLC		
Operator Info	Calgary Energy, LLC 4444 E. 146th St. N. Skiatook, OK 74070 Phone: 918-798-4511	Inventory ID	OS1077000		
		API Well No			
		Lease Name	Tidal Osage I		
		Well ID	TO-4-15		
Location	SE 23 24N 08E	Status	Inactive	Well Type	Disposal
Latitude	36.541958	Longitude	-96.411714		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	Calgary Energy, LLC		
Inspect No.		Date Last MIT	05/01/2019	Last Test Result	Acceptable
Casing	4.5	Tubing	2.375	USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 589
FLM Canister Pressure		Actual Pressure	Max Volume		
Lease Status	Active	Determined?	Max Inj Units Barrels Per Month		
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Calgary Energy, LLC ran 2217.25 feet of 1-inch tubing into the well and pumped 24 sacks of cement, then pulled 34 joints of the 1-inch tubing out of the hole. The operator pumped an additional 35 sacks of cement, but the cement did not circulate to the surface. The operator shut down for the day and agreed to return the following morning to tag and verify the top of cement with the 1-inch tubing, then resume plugging operations.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.541958, -96.411714		
City: Wynona	County/Parish: Osage	State: Oklahoma



Photo File Name: DSCN0668

Orientation: NW

Date of Photo: 08/11/2022

Time of Photo: 12:30 PM

Latitude: 36.541958

Longitude: -96.411714

Photographer: Matthew Allen

Description: This was a photo of well OS1077000 (Tidal Osage 1 – 4-W15). This photo shows the workover rig setup on the well, the plastic lined catchpit on the north edge of the well location and the cement pumping line connected to the 1-inch tubing which has been run to total depth to begin pumping cement.