

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	02/15/2023	Time	17:55
Inspection Due	2019-11-20T00:00:00Z	Operator Representative	Contango Resources, LLC		
Operator Info	Contango Resources, LLC 1717 South Boulder, Suite 900 Tulsa, OK 74119 Phone: 918-392-3396	Inventory ID	OS4106000		
		API Well No			
		Lease Name	Gale		
		Well ID	GALE 14		
Location	NE 28 27N 06E	Status	Active	Well Type	Enhanced Recovery
Latitude	36.794713	Longitude	-96.660296		
Inspection Reason	MIT		Responsible Company at Time of Inspection	Contango Resources	
Inspect No.		Date Last MIT	11/20/2017	Last Test Result	Acceptable
Casing	4.5	Tubing	2.375	USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 799
FLM Canister Pressure		Actual Pressure	0	0	Max Volume
Lease Status	Active	Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector witnessed Standard Annulus Pressure Test (SAPT) on well OS4106000. Pressure, hold OK. I observed no areas of concern at the time of the inspection. EPA enforcement staff will review inspection data to determine compliance with EPA UIC regulations. Post Workover MIT Replaced tubing from steel to plastic lined steel, replaced standard packer with nickel plated packer. Initial: 300psi Mid: 295psi Final: 295psi Pressure Hold OK Total flowback: 6450ml Packer Depth: 2824				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.794713, -96.660296		
City: Shidler	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010079

Orientation: S

Date of Photo: 02/15/2023

Time of Photo: 5:56 PM

Latitude: 36.794713

Longitude: -96.660296

Photographer: Matthew Allen

Description: This was well OS4106000 at the time of the inspection.