

To: Rodger Collins

From: Keith Bailey


Date: July 21, 1993

VISTA**Interoffice
Communication**

Subject: **Bleeder Valves in VCM Service**

During the last quarterly VCM Bleeder Valve Survey, five valves were found to be unplugged. Unplugged valves could result in substantial regulatory fines. Therefore it is important that the plug in the valve be replaced when it is removed during equipment or line servicing. Please remind shift supervisors of the importance of following this policy.

If there are any questions or comments please let me know.



Keith Bailey
Co-op Process Engineer

CC: JEN, KGA, TRM, JDO, WSC