

Inspection Report Addendum for Well: MT20000-01153
Inspection Date: 10/24/2023

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20000-01153 (9-W2), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/24/2023			
Photo No. 1 of 6	Time: 1:17 pm		
Photo Description: Well sign by wellhead.			

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20000-01153 (9-W2), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/24/2023			
Photo No. 2 of 6	Time: 1:17 pm		
Photo Description: Wellhead is observed to be disconnected from flowline (left of the well).			

Inspection Report Addendum for Well: MT20000-01153
Inspection Date: 10/24/2023

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20000-01153 (9-W2), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/24/2023			
Photo No. 3 of 6	Time: 1:18 pm		
Photo Description: Closer view of wellhead. Tubing master ball valve stem observed to be in open position.			

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20000-01153 (9-W2), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/24/2023			
Photo No. 4 of 6	Time: 1:18 pm		
Photo Description: Tubing was opened to atmosphere during inspection. However, valve was iced over, plugging communication to atmosphere.			

Inspection Report Addendum for Well: MT20000-01153
Inspection Date: 10/24/2023

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20000-01153 (9-W2), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/24/2023			
Photo No. 5 of 6	Time: 1:19 pm		
Photo Description: Ice plug was removed to expose tubing to atmosphere. No pressure was observed in tubing.			

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20000-01153 (9-W2), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/24/2023			
Photo No. 6 of 6	Time: 1:18 pm		
Photo Description: Tubing-casing annulus observed to be maintained continuously open to atmospheric pressure.			

LIANG
 Digitally signed
 by LIANG WANG
 Date: 2023.11.20
 11:25:16 -07'00'
WANG

 Inspector signature

 Inspector signature

 Inspector signature