

Inspection Report
Mechanical Integrity Test
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas TX 75270

Inspector Matthew Allen		MIT Date 10/02/2025		Time 09:15	
Operator Representative Ceja Corporation		Report Sent Operator			
Inject Interval 3312 - 3338		USDW 265		Well Type Enhanced Recovery	
Annulus Fluid Type Casing 5.5		Concentric Pkr Tubing		Packer Depth 2776	

Operator Info Ceja Corporation 1437 South Boulder, Suite 1250 Tulsa, OK 74119 Phone: 918-496-0770	Inventory ID OS0103000 API Well No Lease Name Well ID 3 Location NE 06 25N 05E
---	---

Type of MIT Ada Pressure Test		Test Reason Routine	
Injecting N	Injection Rate (bpd)	Tubular Lining	Ann Filled (hrs)
MIT Due	MIT Freq EVERY FIVE YEARS	Ann Press Mont	

Time	Tubing Pressure	Annulus Pressure	Flowback	Pressure	Volume
Pre-Test	0	300	High		
Initial 09:30	1200	300	Mid		
Mid 09:45	1200	300	Low		
Final 10:00	1200	300	End		
			Total Volume		

	ADA Pressure Test - Required Test Pressure (Fluid Column Ht * Specific Gravity * .433 / N2 Wt Fac = Required Test Pressure)																								
	<table style="width: 100%;"> <tr> <th style="width: 80%;"></th> <th style="width: 10%;">Tubing</th> <th style="width: 10%;">Annulus</th> </tr> <tr> <td>Depth to Top Perf/Open Hole</td> <td>3312</td> <td></td> </tr> <tr> <td>Depth to Fluid Level</td> <td>313</td> <td></td> </tr> <tr> <td>Fluid Column Level</td> <td>2999</td> <td></td> </tr> <tr> <td>Specific Gravity of Fluid</td> <td>1.06</td> <td></td> </tr> <tr> <td>Nitrogen Weight Factor</td> <td>1.11</td> <td></td> </tr> <tr> <td>Required Pressure Test</td> <td>1240</td> <td></td> </tr> <tr> <td>Remedial Action Type</td> <td></td> <td></td> </tr> </table>		Tubing	Annulus	Depth to Top Perf/Open Hole	3312		Depth to Fluid Level	313		Fluid Column Level	2999		Specific Gravity of Fluid	1.06		Nitrogen Weight Factor	1.11		Required Pressure Test	1240		Remedial Action Type		
	Tubing	Annulus																							
Depth to Top Perf/Open Hole	3312																								
Depth to Fluid Level	313																								
Fluid Column Level	2999																								
Specific Gravity of Fluid	1.06																								
Nitrogen Weight Factor	1.11																								
Required Pressure Test	1240																								
Remedial Action Type																									

Fluid Migration Test Type		Remedial Action Type	
----------------------------------	--	-----------------------------	--

Inspection Comments	Well, OS0103000 achieved an acceptable test pressure of 1200psig and maintained the pressure for the duration of the required 30-minute observance period. There were no areas of concern at the time of the inspection.
----------------------------	--

Inspector Signature	MATTHEW ALLEN Digitally signed by MATTHEW ALLEN Date: 2025.12.10 09:32:14 -06'00'
Supervisor Signature	JEANNE ECKHART Digitally signed by JEANNE ECKHART Date: 2025.12.10 12:56:58 -06'00'

Appendix 1

Photograph Log 1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.676548, -96.804222		
City: Burbank	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010758

Orientation: S

Date of Photo: 9/27/2025

Time of Photo: 9:15AM

Latitude: 36.676548

Longitude: -96.804222

Photographer: Matthew Allen

Description: This was well OS0103000, there were no areas of concern at the time of the inspection.