


UNION CARBIDE CORPORATION
SOUTH CHARLESTON PLANT
Safety and Health Department
South Charleston, West Virginia 25303



August 12, 1987

TO: D. H. Ott

CC: B. N. Gliatta*
M. J. Shoger*

Re: SHARE Inspection Results

Dear Dave:

You will find attached a copy of the findings from the SHARE inspection held August 12, 1987. Thank you for the cooperation of your staff and hourly folke in making the audit meaningful.

The program goals are that the following items be satisfied by your department:

1. All deficiencies must be addressed within ninety (90) days of the inspection; and
2. An update is sent to the SHARE coordinator and your APM each thirty (30) days after the inspection until completion. You can use a copy of this report and the spaces below in summarizing your completion progress.

I trust that you will find this program worth supporting to continue to maintain and improve our plant facilities and safety. If you have any questions or need help in understanding the requirements/specifications contained within, please contact me at your earliest convenience.

Steve K.

S. B. Kovach
SHARE Coordinator

PROGRESS UPDATE

	30 Days (Sep. 12, 1987)	60 Days (Oct. 12, 1987)	90 Days (Nov. 12, 1987)
% Complete	_____	_____	_____
Signature	_____	_____	_____

Send copy of update to: B. N. Gliatta - Bldg. 82-3
S. B. Kovach - Bldg. 109-2

SBK/yc
1658A

Attachment

*Copy of letter only

UCC 008474

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

Department Title Muse 4 Polys Dept. No. 10600 Location 196 Date of Inspection 8/12/83
 Inspector Submitting Report H. H. P. P. Phone 9953 Responsibility Insulation Date of Report 8/13/83

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan		
			Action Steps or Explanation	Date Correct	Shop Order Number
1N1	Exposed ins. at 8th over head North 1st Floor		Patch & Seal		
1N2	Exposed ins. N. No. 7 Cat Back Mix. at 1st Cat Bed Mix. 1st Floor		Patch & Seal		
1N3	Metal Weather Barrier on N. side of still column needs Repair		Repair		
1N4	Repaired 3rd Land Condensate Blowing on it. Exposed top stairs East End Needs Repairs.		Repair		
1N5	Exposed Unibestos West Elect Switch Rack West 2nd	✓	Remove & Replace		