

A U T O M O T I V E D A T A B O O K B U L L E T I N #3-941
December 20, 1994

			FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
ACURA					
1995, Integra			7493-D617**	D/D	7443-D564**
1995, Legend			7382-D503**	D/D	7418-D536**
AUDI					
1995, 90			7352-D419**	D/D	7309-D228**
1995, 90 Quattro			7352-D419**	D/D	7309-D228**
1995, A6			7306-D419**	D/D	7309-D228**
	OR		7434-D555**	D/	
1995, Cabriolet			7352-D419**	D/D	7309-D228**
BUICK					
1995, Century			7136-D215**	D/N	1394-S636
1995, LeSabre			7384-D623**	D/N	1394-S636
1995, Park Avenue			7384-D623**	D/N	1394-S636
1995, Regal			7265-D376**	D/D	7387-D508**
1995, Roadmaster			7214A-D52	D/BH	2134BTT-S652
1995, Skylark			7385-D506**	D/BH	2164-553
CADILLAC					
1995, DeVille			7384-D623**	D/D	7387-D508**
1995, Eldorado			7384-D623**	D/D	7387-D508**
1995, Seville			7384-D623**	D/D	7387-D508**
CHEVROLET					
1995, Beretta			7385-D506**	D/BH	2164-553
1995, Camaro			7384-D623**	D/BH	2117BTT-S651
	OR			/D	7301-D413**
1995, Caprice			7214A-D52	D/BH	2117BTT-S650
	OR			/BH	2134BTT-S652
	OR			/D	7505-D628**
1995, Cavalier			7385-D506**	D/BH	2164-553
1995, Corsica			7385-D506**	D/BH	2164-553
1995, Corvette			7300-D412**	D/D	7301-D413**
1995, Lumina Minivan			7384-D623**	D/N	1394-S636
1995, Monte Carlo			7265-D376**	D/N	1394-S636
CHEVROLET TRUCK/GMC TRUCK					
Astro/Safari	2WD	1995	7214A-D52	D/BH	2117BTT-S651
Astro/Safari	4WD	1995	7259-D369**	D/BH	2117BTT-S651
Blazer/Jimmy	2WD	1995	7480A-D202	D/BH	2117BTT-S651
Blazer/Jimmy	4WD	1995	7480A-D202	D/BH	2117BTT-S651
S10/Sonoma	2WD	1995	7480A-D202	D/BH	2117BTT-S651
T10/Sonoma	4WD	1995	7480A-D202	D/BH	2117BTT-S651
Tahoe/Yukon		1995	7259-D369**	D/N	1404A-S675
C1500/Sierra	C1500	1995	7259-D369**	D/N	1404A-S675
K1500/Sierra	K1500	1995	7259-D369**	D/N	1404A-S675
		OR		/BH	2073AT-S653

SEE DISCLAIMER AT END OF BULLETIN

FMSI® and FMS® are registered trademarks of the Friction Materials Standards Institute, Inc.

Copyright® by Friction Materials Standards Institute, Inc.

		FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>CHEVROLET TRUCK/GMC TRUCK (con't)</u>				
C2500/Sierra C2500	1995	7259-D369**	D/BH	2073AT-S653
	OR	7260-D370**	D/BH	2042BT-S655
K2500/Sierra K2500	1995	7259-D369**	D/BH	2073AT-S653
	OR	7260-D370**	D/BH	2042BT-S655
C3500/Sierra C3500	1995	7260-D370**	D/BH	2042BT-S655
	OR		/BH	2157AT-S656
K3500/Sierra K3500	1995	7260-D370**	D/BH	2042BT-S655
	OR		/BH	2157AT-S656
C/K3500 DRW	1995	7339-D459**	D/BH	2157AT-S656
	OR	7081-D149**	D/D	7081-D149**
Suburban C/K1500	1995	7259-D369**	D/N	1404A-S675
	OR	7260-D370**	D/BH	2073AT-S653
Suburban C/K2500	1995	7259-D369**	D/BH	2073AT-S653
	OR	7260-D370**	D/BH	2042BT-S655
G10 Van/G1500 Van	1995	7214A-D52	D/BH	2073AT-S653
G20 Van/G2500 Van	1995	7214A-D52	D/BH	2073AT-S653
G30 Van/G3500 Van	1995	7280A-D392	D/BH	2042BT-S655
	OR	7081A-D149	D/BH	2157AT-S656
<u>CHRYSLER (See Comments)</u>				
1995, Concorde		7470A-D642	D/D	7438A-D658 (Note #6)
1995, LHS		7470A-D642	D/D	7438A-D658
1995, New Yorker		7470A-D642	D/D	7438A-D658
<u>DODGE (See Comments)</u>				
1995, Intrepid		7470A-D642	D/N	1456-S657*
	OR		/D	7438A-D658
<u>DODGE TRUCK</u>				
Ram 1500	1995	7259-D369**	D/BH	2134ATT-S652
Ram 2500	1995	7260-D370**	D/BH	2042BT-S655
	OR	7339-D459**	D/	
Ram 3500	1995	7339-D459**	D/BH	2157AT-S656
Ram 1500 4WD	1995	7259-D369**	D/BH	2134ATT-S652
Ram 2500 4WD	1995	7260-D370**	D/BH	2042BT-S655
	OR	7339-D459**	D/	
Ram 3500 4WD	1995	7339-D459**	D/BH	2157AT-S656
Ram Van B150	1995	7179A-D269	D/BH	2025T-446
Ram Van B250	1995	7179A-D269	D/BH	2025T-446
Ram Van B350	1995	7179A-D269	D/BH	2146AT-357
	OR		/BH	2140AT-358
Dakota 2WD	1995	7410A-D593	D/BH	2176T-538
Dakota 4WD	1995	7410A-D593	D/BH	2089T-445*
<u>EAGLE</u>				
1995, Vision		7470A-D642	D/D	7438A-D658
<u>FORD TRUCK (See Corrections)</u>				
Explorer 1995		7532-D652** (Notes #1 & #3)	D/	
Ranger 1995		7532-D652**	D/	
Windstar 1995		7536-D656** (Notes #2 & #4)	D/	
<u>GEO</u>				
1995, Prism		7441-D562**	D/N	8105-597*

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>HONDA</u>			
1995, Accord Coupe	7345-D465**	D/N	1429-S627*
OR		/D	7418-D537**
1995, Accord Sedan	7345-D465**	D/N	1429-S627*
OR		/D	7418-D537**
1995, Accord Wagon	7382-D503**	D/N	1429-S627*
OR		/D	7418-D537**
<u>HYUNDAI</u>			
1995, Sonata	7329-D449**	D/N	1400-578*
OR		/D	7236-D342**
<u>ISUZU</u>			
1995, Rodeo	7347-D363**	D/N	1360-S619*
OR	7459-D579**	D/D	7460-D580**
<u>MAZDA</u>			
1995, MX6	7515-D637**	D/N	1407-S667*
OR		/D	7464-D584**
1995, RX7	7465-D585**	D/D	7186-D482**
1995, 626	7515-D637**	D/N	1407-S667*
OR		/D	7464-D584**
1995, 929	7431-D552**	D/D	7432-D553**
<u>NISSAN</u>			
1995, 240SX	7307-D422**	D/D	7146-D272**
1995, 300ZX	7340-D647**	D/D	7341-D461**
<u>OLDSMOBILE</u>			
1995, Cutlass Supreme	7265-D376**	D/D	7387-D508**
1995, Cutlass Ciera	7136-D215**	D/N	1394-S636
1995, Achieva	7385-D506**	D/BH	2164-553
1995, Eighty Eight	7384-D623**	D/N	1394-S636
1995, Ninety Eight	7384-D623**	D/N	1394-S636
1995, Silhouette	7384-D623**	D/N	1394-S636
<u>PONTIAC</u>			
1995, Bonneville	7384-D623**	D/N	1394-S636
1995, Firebird	7384-D623**	D/BH	2117BTT-S651
OR		/D	7301-D413**
1995, Grand Am	7385-D506**	D/BH	2164-553
1995, Grand Prix	7265-D376**	D/D	7387-D508**
1995, Sunfire	7385-D506**	D/BH	2164-553
1995, Trans Sport	7384-D623**	D/N	1394-S636
<u>SATURN (See Comments)</u>			
1995	7386-D507**	D/N	1437-S637*
OR		/D	7387-D508**
<u>TOYOTA (See Comments & Corrections)</u>			
1995, Corolla	7441-D562**	D/N	8105-597*
1995, Paseo	7153-D242**	D/N	1439-S642*
1995, Celica	7441-D562**	D/N	8104-588*
OR	7357-D476**	D/D	7223-D325**
1994-92, MR2 Turbo		/D	7409-D657**
			(Note #5)
1995, T100 1/2T 2WD	7485-D604**	D/N	1397-589*
1995, T100 1/2T 4x4	7298-D611**	D/N	1397-589*
1995, T100 1T 2WD	7486-D605**	D/N	1383-549*

C O M M E N T S

FMSI 7386-D507 front disc brake on Saturn has changed with respect to hardware - Sets for 1994-91 applications had 4 sensors (2LH,2RH) - Set for 1995 application has 8 sensors (4LH,4RH). This will be noted in the illustration section of next catalog.

Existing lining used with new shoe:

<u>Lining</u>	<u>Assembly</u>	<u>Application</u>
7409	7409-D657	1994-92 Toyota MR2 Turbo Rear
7438A	7438A-D658	1995 Chrysler Concord, LHS, New Yorker Rear
		1995 Dodge Intrepid Rear
		1995 Eagle Vision Rear

Existing lining with existing shoe - Not previously combined:

<u>Lining</u>	<u>Assembly</u>	<u>Application</u>
7470A	7470A-D642	1995 Chrysler Concord, LHS, New Yorker Front
		1995 Dodge Intrepid Front
		1995 Eagle Vision Front

C O R R E C T I O N S

1995 Ford Windstar - application information published in Bulletin #1-941 for front brake is incorrect. The correct FMSI number is 7536-D656.

Catalog 941 shows 1993 Toyota MR2 Turbo rear as FMSI 7409-D528. The correct assignment is 7409-D657.

DISC BRAKE LINING ASSIGNMENTS

Note #1	<u>FMSI 7532</u>	7532-D652
	43.6 x 16.5 x 136.0	4 IM
	(1.72 x .650 x 5.35)	
Note #2	<u>FMSI 7536</u>	7536-D656
	50.5 x 17.0 x 117.9	4 IM
	(1.99 x .669 x 4.64)	

DISC BRAKE SHOE ASSIGNMENTS

Note #3	<u>FMS D652</u>	7532-D652	Ford Truck
	154.0 x 6.4		
	(6.06 x .252)		
Note #4	<u>FMS D656</u>	7536-D656	Ford Truck
	124.0 x 5.6		
	(4.88 x .220)		
Note #5	<u>FMS D657</u>	7409-D657	Toyota
	98.6 x 6.1		
	106.9 x 5.5		
	(3.88 x .240)		
	(4.21 x .217)		
Note #6	<u>FMS D658</u>	7438A-D658	Chrysler
	133.7 x 4.8		Dodge
	(5.26 x .189)		Eagle

CLUTCH FACING APPLICATIONS BY MODELACURA

1991-90, Integra 8063
(Note #11)
1991-90, Legend 8062
(Note #10)

BMW

1988-85, 500 Series 3.5L 9061
(Note #18)
1987-85, 600 Series 3.5L 9061
1986-85, 700 Series 3.5L 9061
1984, 700 Series 3.3L 9061

CHEVROLET TRUCK

Truck 11025
(Note #19)

JOHN DEERE

P.T.O. 8068
(Note #16)

GEO

1993, GEO 8069
(Note #17)

GMC TRUCK

Truck 11025

HINO

Truck 1286
(Note #7)
Truck 11025

ISUZU

Truck 8.4L 1449
(Note #8)

PORSCHE

1988-70, Porsche 8066
(Note #14)

TOYOTA

Toyota 8064
(Note #12)
Toyota 8065
(Note #13)
1993, Toyota 8069
1983-82, Toyota 8069

VOLKSWAGEN

1987-84, Golf 8061
(Note #9)
1989-81, Volkswagen 8067
(Note #15)

CLUTCH FACING ASSIGNMENTS

Note #7	<u>FMSI 1286</u>	12.81	x	8.26	x	.142	36 DGEP	-	36
Note #8	<u>FMSI 1449</u>	14.96	x	9.44	x	.180	36 DGAP	-	36
Note #9	<u>FMSI 8061</u>	8.26	x	5.30	x	.135	16 Gr A Str	-	16
Note #10	<u>FMSI 8062</u>	8.83	x	5.93	x	.135	16 Gr A Str	-	16
Note #11	<u>FMSI 8063</u>	8.65	x	5.93	x	.135	16 Gr A Str	-	16
Note #12	<u>FMSI 8064</u>	8.85	x	5.93	x	.138	16 Gr A Str	-	16
Note #13	<u>FMSI 8065</u>	8.88	x	6.33	x	.137	16 Gr A Str	-	16
Note #14	<u>FMSI 8066</u>	8.98	x	5.95	x	.137	16 Gr A Str	-	16
Note #15	<u>FMSI 8067</u>	8.27	x	5.77	x	.136	16 Gr A Str	-	16
Note #16	<u>FMSI 8068</u>	8.86	x	6.30	x	.124	16 Gr A Str	-	16
Note #17	<u>FMSI 8069</u>	8.36	x	5.51	x	.134	16 Gr A Str	-	16
Note #18	<u>FMSI 9061</u>	9.42	x	6.13	x	.150	16 Gr A Str	-	16
Note #19	<u>FMSI 11025</u>	11.75	x	7.56	x	.159	36 DGAP	-	36

The data shown in this bulletin has been supplied by sources considered to be reliable. While we believe that such information is correct, the Institute cannot and does not accept any responsibility or liability for errors or omissions, or harm resulting therefrom.

The data shown in this bulletin indicates dimensions only and in no way refers to quality of any materials that may be embodied in the product or particular application involved, and moreover SINCE FIELD CONDITIONS AND OTHER FACTS MAY NECESSARILY VARY FROM ONE APPLICATION TO ANOTHER, FRICTION MATERIALS SUPPLIERS AND INSTALLERS SHOULD RELY ULTIMATELY AND SOLELY UPON THEIR OWN EXPERTISE AND JUDGMENT AS TO QUALITY AND DIMENSIONAL SIZE. Under no circumstances should replacement items be used when they do not appear to fit, nor be "forced" to fit, nor be modified in the field instead of obtaining a proper sized item from a supplier. If such items are modified in the field to fit, the Institute specifically disclaims all liability and responsibility for any harm resulting therefrom.

If any error or omission is noted in this bulletin, it should be reported immediately to the Friction Materials Standards Institute, Inc., 588 Monroe Turnpike, Monroe, Connecticut 06468.