

ABERDEEN PVC PLANT
NEW EMPLOYEE SAFETY ORIENTATION
TRAINING CHECKLIST

A

- | | | | |
|---------|----------------------------------|--|--|
| ✓(1) | ABERDEEN SAFETY ORIENTATION SHOW | PARTS 1, 4 & 5 (no process) | ☒ J.V.D. |
| JGR (2) | HEALTH SHOWS: | VCM
LEAD
TOSCA
(have Steve Hillman take TOSCA) | ☒ J.R.
☒ J.R.
☒ J.R.
delete |
| ✓ (3) | SAFETY RULE BOOKS: | CONOCO
ABERDEEN | ☒ J.V.D.
☒ J.V.D. |
| ✓ (4) | DUPONT SAFETY ORIENTATION (#500) | PASS OUT - BRIEF INTRODUCTION
(Don't cover rules)
PASS OUT - TELL TO DO
AT HOME | ☒ J.V.D.
☒ J.V.D. |
| (5) | LIFTING: | NSC BOOKLET
DISCUSSION | ☒ J.V.D. |
| CP (6) | FORKLIFT TRAINING: | SHOW
FIELD | ☒ J.R.
☒ J.R. |
| (7) | ELECTRICAL LOCKOUT: | ALLIED CHEMICAL FILM
REVIEW OF ABERDEEN LOCKOUT PROCEDURE | ☒ J.V.D.
☒ J.V.D. |
| JGR (8) | RESPIRATOR TRAINING: | SCOTT AIR PACK
FRESH AIR
DUST | ☒ J.R.
☒ J.R.
☒ J.R.</ |

16. VCM cannister masks may be used in VCM concentrations below 10 ppm for up to 10 hours. They must not be used in higher concentrations except to escape from danger. ☒ True ☐ False
17. Air-line respirators may be used in VCM concentrations of no more than 1000 ppm. They must not be used in unknown concentrations. ☒ True ☐ False
18. Scott Air Paks must be worn in VCM concentrations above 1000 ppm. They must also be worn in unknown concentrations. ☒ True ☐ False
19. Breathing high concentrations of VCM can cause you to pass out. ☒ True ☐ False
20. One of the purposes of the medical surveillance program is to detect the symptoms of VCM related illness as early as possible. ☒ True ☐ False

16. VCM cannister masks may be used in VCM concentrations below 10 ppm for up to 10 hours. They must not be used in higher concentrations except to escape from danger.
17. Air-line respirators may be used in VCM concentrations of no more than 1000 ppm. They must not be used in unknown concentrations.
18. Scott Air Paks must be worn in VCM concentrations above 1000 ppm. They must also be worn in unknown concentrations.
19. Breathing high concentrations of VCM can cause you to pass out.
20. One of the purposes of the medical surveillance program is to detect the symptoms of VCM related illness as early as possible.

☒ True ☐ False

☒ True ☐ False

☒ True ☐ False

☒ True ☐ False

☒ True ☐ False

16. VCM cannister masks may be used in VCM concentrations below 10 ppm for up to 10 hours. They must not be used in higher concentrations except to escape from danger.

☒ True

☒ False

17. Air-line respirators may be used in VCM concentrations of no more than 1000 ppm. They must not be used in unknown concentrations.

☒ True

☒ False

18. Scott Air Paks must be worn in VCM concentrations above 1000 ppm. They must also be worn in unknown concentrations.

☒ True

☐ False

19. Breathing high concentrations of VCM can cause you to pass out.

☒ True

☐ False

20. One of the purposes of the medical surveillance program is to detect the symptoms of VCM related illness as early as possible.

☒ True

☐ False

16. VCM cannister masks may be used in VCM concentrations below 10 ppm for up to 10 hours. They must not be used in higher concentrations except to escape from danger.

X True _____ False

17. Air-line respirators may be used in VCM concentrations of no more than 1000 ppm. They must not be used in unknown concentrations.

X True _____ False

18. Scott Air Paks must be worn in VCM concentrations above 1000 ppm. They must also be worn in unknown concentrations.

X True _____ False

19. Breathing high concentrations of VCM can cause you to pass out.

X True _____ False

20. One of the purposes of the medical surveillance program is to detect the symptoms of VCM related illness as early as possible.

X True _____ False

16. VCM cannister masks may be used in VCM concentrations below 10 ppm for up to 10 hours. They must not be used in higher concentrations except to escape from danger.

_____ True X False

17. Air-line respirators may be used in VCM concentrations of no more than 1000 ppm. They must not be used in unknown concentrations.

X True _____ False

18. Scott Air Paks must be worn in VCM concentrations above 1000 ppm. They must also be worn in unknown concentrations.

_____ True X False

19. Breathing high concentrations of VCM can cause you to pass out.

X True _____ False

20. One of the purposes of the medical surveillance program is to detect the symptoms of VCM related illness as early as possible.

X True _____ False

- (12) The lead materials used in the plant are not absorbed through the skin. True(☒) False()
- (13) The use of compressed air for cleaning lead contaminated dusts is prohibited. True(☒) False()
- (14) Lead used in this plant can enter the body by (Circle a, b, c, d, or e):
- a. Breathing
 - b. Swallowing
 - c. Absorbing through the skin.
 - d. All of the above.
 - e. a & b only.
- (15) Overhead vent fans and exhaust hoods must be kept running when making compound or dry blend. True(☒) False()
- (16) You are permitted to take food, drinks, etc. into lead work areas, provided you keep them covered up to prevent lead contamination. True() False(☒)
- (17) It is important to your health for you to create as little dust as possible when handling empty lead containers such as bags. True(☒) False()
- (18) You must clean and test your 3M Airhat at least daily, at the end or the beginning of your shift. True(☒) False()
- (19) If you can't see any lead dust on your hands or clothing, you can be sure there's not enough on you to worry about. True() False(☒)
- (20) Responsibility for controlling employee exposure to lead rests on:
(Choose a, b, c, d, e or f)
- a. The Company
 - b. The Employee
 - c. The Environmental Protection Agency (EPA)
 - d. Both a. & c.
 - e. Both a. & b.
 - f. Both b. & c.

- (12) The lead materials used in the plant are not absorbed through the skin. True~~X~~ False()
- (13) The use of compressed air for cleaning lead contaminated dusts is prohibited. True~~X~~ False()
- (14) Lead used in this plant can enter the body by (Circle a, b, c, d, or e.):
- a. Breathing
 - b. Swallowing
 - c. Absorbing through the skin.
 - d. All of the above.
 - ☒ e. a & b only.
- (15) Overhead vent fans and exhaust hoods must be kept running when making compound or dry blend. True~~X~~ False()
- (16) You are permitted to take food, drinks, etc. into lead work areas, provided you keep them covered up to prevent lead contamination. True() False~~X~~
- (17) It is important to your health for you to create as little dust as possible when handling empty lead containers such as bags. True~~X~~ False()
- (18) You must clean and test your 3M Airhat at least daily, at the end or the beginning of your shift. True~~X~~ False()
- (19) If you can't see any lead dust on your hands or clothing, you can be sure there's not enough on you to worry about. True() False~~X~~
- (20) Responsibility for controlling employee exposure to lead rests on:
(Choose a, b, c, d, e, or f)
- a. The Company
 - b. The Employee
 - c. The Environmental Protection Agency (EPA)
 - d. Both a. & c.
 - ☒ e. Both a. & b.
 - f. Both b. & c.

- (12) The lead materials used in the plant are not absorbed through the skin. True~~(X)~~ False()
- (13) The use of compressed air for cleaning lead contaminated dusts is prohibited. True() False~~(X)~~
- (14) Lead used in this plant can enter the body by (Circle a, b, c, d, or e.):
- a. Breathing
 - b. Swallowing
 - c. Absorbing through the skin.
 - d. All of the above.
 - ☒ e. a & b only.
- (15) Overhead vent fans and exhaust hoods must be kept running when making compound or dry blend. True~~(X)~~ False()
- (16) You are permitted to take food, drinks, etc. into lead work areas, provided you keep them covered up to prevent lead contamination. True() False~~(X)~~
- (17) It is important to your health for you to create as little dust as possible when handling empty lead containers such as bags. True~~(X)~~ False()
- (18) You must clean and test your 3M Airhat at least daily, at the end or the beginning of your shift. True~~(X)~~ False()
- (19) If you can't see any lead dust on your hands or clothing, you can be sure there's not enough on you to worry about. True() False~~(X)~~
- (20) Responsibility for controlling employee exposure to lead rests on:
(Choose a, b, c, d, e, or f)
- a. The Company
 - b. The Employee
 - c. The Environmental Protection Agency (EPA)
 - d. Both a. & c.
 - ☒ e. Both a. & b.
 - f. Both b. & c.

- (12) The lead materials used in the plant are not absorbed through the skin. True(☒) False()
- (13) The use of compressed air for cleaning lead contaminated dusts is prohibited. True(☒) False(☒)
- (14) Lead used in this plant can enter the body by (Circle ☒ a, b, c, d, or e.):
- a. Breathing
 - b. Swallowing
 - c. Absorbing through the skin.
 - d. All of the above.
 - e. a & b only.
- (15) Overhead vent fans and exhaust hoods must be kept running when making compound or dry blend. True(☒) False()
- (16) You are permitted to take food, drinks, etc. into lead work areas, provided you keep them covered up to prevent lead contamination. True() False(☒)
- (17) It is important to your health for you to create as little dust as possible when handling empty lead containers such as bags. True(☒) False()
- (18) You must clean and test your 3M Airhat at least daily, at the end or the beginning of your shift. True(☒) False()
- (19) If you can't see any lead dust on your hands or clothing, you can be sure there's not enough on you to worry about. True(☒) False(☒)
- (20) Responsibility for controlling employee exposure to lead rests on:
(Choose a, b, c, d, e, or f)
- a. The Company
 - b. The Employee
 - c. The Environmental Protection Agency (EPA)
 - d. Both a. & c.
 - ☒ e. Both a. & b.
 - f. Both b. & c.

(12) The lead materials used in the plant are not absorbed through the skin. True(✓) False()

(13) The use of compressed air for cleaning lead contaminated dusts is prohibited. True(✓) False(✓)

(14) Lead used in this plant can enter the body by (Circle a, b, c, d, or e):

- a. Breathing
- b. Swallowing
- c. Absorbing through the skin.
- d. All of the above.
- e. a & b only.

(15) Overhead vent fans and exhaust hoods must be kept running when making compound or dry blend. True() False(✓)

(16) You are permitted to take food, drinks, etc. into lead work areas, provided you keep them covered up to prevent lead contamination. True() False(✓)

(17) It is important to your health for you to create as little dust as possible when handling empty lead containers such as bags. True(✓) False()

(18) You must clean and test your 3M Airhat at least daily, at the end or the beginning of your shift. True() False(✓)

(19) If you can't see any lead dust on your hands or clothing, you can be sure there's not enough on you to worry about. True() False(✓)

(20) Responsibility for controlling employee exposure to lead rests on: (Choose a, b, c, d, e, or f)

SECTION II QUIZ

- T 16. Always cross railroad tracks at a 45 degree angle.
- T 17. Passengers should never be carried on a forklift truck as it is designed for only one person...the operator.
- T 18. Before depositing a load, the operator should take the time to inspect the place where he is going to unload.
- T 19. You should never use full back tilt when high stacking. The safest condition is when the top of the mast is only a foot to 18 inches back from vertical.
- T 20. If you have to leave the fork truck unattended for even a short time, you should lower the forks and turn off the engine.

