

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	01/18/2023	Time	13:40
Inspection Due	2020-02-14T00:00:00Z	Operator Representative	CapturePoint, LLC (formerly Perdure Petroleum, LLC)		
Operator Info	CapturePoint, LLC (formerly Perdure Petroleum, LLC) 1101 Central Expwy S., Suite 150 Allen, TX 75013 Phone: 832-300-8221	Inventory ID	OS0434000		
		API Well No			
		Lease Name	NBU		
		Well ID	66-W2		
Location	SW 25 27N 05E	Status	Active	Well Type	Enhanced Recovery
Latitude	36.784487	Longitude	-96.719976		
Inspection Reason	MIT	Responsible Company at Time of Inspection	CapturePoint, LLC		
Inspect No.		Date Last MIT	02/14/2018	Last Test Result	Acceptable
Casing	3.5	Tubing	2.0625	USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 815
FLM Canister Pressure		Actual Pressure	180	0	Max Volume
Lease Status	Active	Determined?	Compan y Gage	Compan y	Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	Y	Injection Rate (bpd)			
Injecting	Y				
Inspection Comments	Inspector witnessed Standard Annulus Pressure Test (SAPT) on well OS0434000. Pressure, hold OK. I observed no areas of concern at the time of the inspection. EPA enforcement staff will review inspection data to determine compliance with EPA UIC regulations. Initial: 450psi Mid: 430psi Final: 430psi Pressure Hold OK Total flowback: 3300ml				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.78449, -96.71998		
City: Shidler	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010047

Orientation: N

Date of Photo: 01/18/2023

Time of Photo: 1:34 PM

Latitude: 36.78449

Longitude: -96.71998

Photographer: Matthew Allen

Description: This was well OS0434000 at the time of inspection.