

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	08/01/2024	Time	09:00
		Operator Representative	CapturePoint, LLC		
Operator Info	CapturePoint, LLC 1101 Central Expwy S., Suite 150 Allen, TX 75013 Phone: 832-300-8221	Inventory ID	OS4674000		
		API Well No			
		Lease Name	Burbank S		
		Well ID	J-W15		
Location	SW 03 25N 06E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.673477	Longitude	-96.64076		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	CapturePoint, LLC		
Inspect No.		Date Last MIT	05/20/2014	Last Test Result	Fail
Casing	5.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 270
FLM Canister Pressure		Actual Pressure			Max Volume
Lease Status	Active	Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed CapturePoint, LLC run tubing in well OS4674000 to 450 feet below the surface and attempt to squeeze 100 sacks of cement. The well would not accept cement squeeze. 50 sacks of cement (2 % calcium) were circulated to the surface from 450 feet. Cement was observed standing at the surface with no fallback.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.673477, -96.64076		
City: Burbank	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010500

Orientation: N/A

Date of Photo: 08/01/2024

Time of Photo: 09:00 AM

Latitude: 36.673477

Longitude: -96.64076

Photographer: Matthew Allen

Description: This was well OS4674000 full of cement to the surface with no fallback.