

Class I and II Well Inspection Form
US Environmental Protection Agency – Region 4
Underground Injection Control Program
61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303
Phone: (404)562-9424

Inspection ID

EPA Well ID#:	F	L	S	1	1	3	0	0	0	9
Year-Month-Day:	2	0	2	2	–	0	9	–	1	3
EPA Permit # (or RA):							6	7	8	
Page	1	Of	2							

Inspector(s): Jason Rose _____ (lead), Page Cirillo _____ Start Time: 11:10 AM _____
_____, _____ End Time: 11:20 AM _____

Facility Contact Information

Facility Name: *Blackjack Plant* _____
Street Address: *4940 Blackjack Plant Road* _____
City: *Jay* _____ County: *Santa Rosa* _____ State: *FL* _____ Zip: *32535* _____
Nature of Business: *Oil and gas production* _____
Facility Owner/Operator: *Black Creek Energy, LLC* _____ Phone: *(601) 431-5386* _____
Email: *harris.butler@butlerroyals.com* _____
Facility Contact (if different): *Michael Wetzel* _____ Phone: *(850) 324-6271* _____
O/O Mailing Address: *140 Virginia Street, Suite 402* _____
City: *Richmond* _____ County: *NA* _____ State: *VA* _____ Zip: *23209* _____

Well Data from File

Well Name & #: *R. L. Moore #23-E* _____
Well Type (see table): *Enhanced Recovery (EOR)* _____ State Permit: API # *0911320121* _____
Latitude (°N): *30.84106039* °N _____ Longitude (°W): *-87.1119759* °W _____ Elevation (ft): *NA* _____
Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing

PBTB 16, 037'

☐ Other: _____
Total Depth (ft): *16,070'* _____ Inner Casing Size (in): *7"* _____ Tubing Size (in): *2.875"* _____ Packer Depth (ft): *15,774'* _____
Inj. Zone: ☐ Open Hole; ☒ Perforated; Top(ft): *15,928'* Bottom(ft): *15,976'* _____ Max. Injection Pressure (psig): *2,500 psi* _____

Field Measurements and Observations

Latitude (°N): *30.840995* °N _____ Longitude (°W): *-87.112166* °W _____ Elevation (ft): *NA* _____
EPA GPS ID: PG No. *3358766066* Well Status (see table): *TA* If not Active, Reported Date Last Active: *Operator did not provide.*
Nature of Injected Fluid(s) if any: _____
General Condition of the Well Site: _____
Notes & Comments (include discrepancies from database values): _____

DEP indicated this well has been temporarily plugged and abandoned, meaning that it is no longer in use, and all perforations have been plugged with cement. The site was clean and well-maintained. There was no evidence of leaks or excessive corrosion. The stairway was unstable, in need of repairs/upgrades.
Perfs (see well schematics):
8/20/1975 4SPF, 12/3/77 2SPF 15,928-15,940' GR
10/13/79 4SPF 15,954-15,976' GR

See reverse for additional observations, comments and photo log

Owner/Operator Representative (Optional)

Name: *Cliff Emmons* _____
Signature & Date: *see attached field notes* _____

UIC Inspector

Name: *Jason Rose* _____
Signature & Date: *Jason Rose* _____ *10/26/22* _____

Inspection ID	EPA Well ID#:	F	L	S	1	1	3	0	0	0	9
	Year-Month-Day:	2	0	2	2	–	0	9	–	1	3
	EPA Permit # (or RA):							6	7	8	
					Page		2	Of		2	

[illegible]

Photographer: Jason Rose _____ EPA Camera ID: PG camera ID no. 14 S/N:31029537 _____

Photo ID: 1 _____ Time: 11:11 AM ____ Lat (°N): NA _____ Long (°W): NA _____

Description: *Looking north, R.L. Moore #23-E sign alongside access road.* _____

Photo ID: 2 _____ Time: 11:11 AM ____ Lat (°N): NA _____ Long (°W): NA _____

Description: *Looking north, site overview showing well head, pressure gauges, valves, and as stairway.* _____

Photo ID: 3 _____ Time: 11:12 AM ____ Lat (°N): NA _____ Long (°W): NA _____

Description: *Looking east, closeup view of surface pressure gauge reading 0 psi.* _____

Photo ID: 4 _____ Time: 11:12 AM ____ Lat (°N): NA _____ Long (°W): NA _____

Description: *Looking east, closeup view of production casing pressure gauge reading 0 psi.* _____

Photo ID: 5 _____ Time: 11:13 AM ____ Lat (°N): NA _____ Long (°W): NA _____

Description: *Looking west, closeup view of internal pressure gauge reading 0 psi.* _____

Photo ID: 6 _____ Time: 11:14 AM ____ Lat (°N): NA _____ Long (°W): NA _____

Description: *Looking south, access stairway with sagging platform.* _____

UIC Inspector

Name: Jason Rose _____

Signature & Date: Jason Rose 10/26/22



Photograph 1: Looking north, R.L. Moore #23-E sign alongside access road.



Photograph 2: Looking north, site overview showing well head, pressure gauges, valves, and access stairway.



Photograph 3: Looking east, closeup view of surface pressure gauge reading 0 psi.



Photograph 4: Looking east, closeup view of production casing pressure gauge reading 0 psi.



Photograph 5: Looking west, closeup view of internal pressure gauge reading 0 psi.



Photograph 6: Looking south, access stairway with sagging platform.