



PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	Aerial Imagery with photo markers
Date Stamp:	3/5/2024
Time Stamp:	NA
Description:	Aerial Imagery with photo markers

Amite BioEnergy (DRAX)

Write a description for your map.

Legend

Drax Biomass Inc. Amite Bioenergy

Feature 1

Google Earth

© 2024 Airbus



PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2892.JPG
Date Stamp:	3/5/2024
Time Stamp:	10:01 AM
Description:	Site map from the SWPPP, which shows three outfall locations. Outfall 004, which is no longer in use but is still covered under the 2021 permit, is not pictured.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2893.JPG
Date Stamp:	3/5/2024
Time Stamp:	10:09 AM
Description:	Site map from the 2022 SPCC Plan. Outfall locations are mislabeled/inconsistent. Outfall locations in the site map shown in DSCN2892 are correct.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2894.JPG
Date Stamp:	3/5/2024
Time Stamp:	11:46 AM
Description:	Retention area upgradient of Outfall 003. Slopes appeared well-stabilized with vegetative cover. The outlet of this riser structure is shown in photo DSCN2895.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2895.JPG
Date Stamp:	3/5/2024
Time Stamp:	11:46 AM
Description:	The retention basin above Outfall 003 (see previous photo) discharges into a vegetated swale and continues in the direction shown here. Additional downgradient views of this conveyance are shown in photos DSCN2912.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2896.JPG
Date Stamp:	3/5/2024
Time Stamp:	11:48 AM
Description:	Additional view of the retention basin of Outfall 003 with well vegetated slopes. Evidence of a minor oil sheen near center right of photo.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2897.JPG
Date Stamp:	3/5/2024
Time Stamp:	11:51 AM
Description:	Looking downgradient at a conveyance near the bark/chip storage and unloading areas. Conveyance discharges into the pond system at Outfall 002 as shown in photo DSCN2898.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2898.JPG
Date Stamp:	3/5/2024
Time Stamp:	11:52 AM
Description:	See photo DSCN2987. View of drainage channel leading to the pond system of Outfall 002.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2899.JPG
Date Stamp:	3/5/2024
Time Stamp:	11:55 AM
Description:	Looking upgradient at the upper pond at Outfall 002. Stockpiles are visible in the background.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2900.JPG
Date Stamp:	3/5/2024
Time Stamp:	11:55 AM
Description:	Looking downgradient at the lower pond at Outfall 002. Baffle was installed near the outlet. A closer view of the pond's riser structure is shown in photo DSCN2901.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2901.JPG
Date Stamp:	3/5/2024
Time Stamp:	11:57 AM
Description:	Outlet structure of Pond #2 was equipped with a floating surface skimmer and an upstream baffle. Outfall 002 is shown in photos DSCN2902-2903.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2902.JPG
Date Stamp:	3/5/2024
Time Stamp:	11:59 AM
Description:	Looking downgradient at Outfall 002. See also photo DSCN2903.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2903.JPG
Date Stamp:	3/5/2024
Time Stamp:	11:59 AM
Description:	Additional view of Outfall 002. Outlet pipe is visible in the leftmost side of the photo. Water travels from photographer's left to right.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2904.JPG
Date Stamp:	3/5/2024
Time Stamp:	12:03 PM
Description:	View of chip storage pile





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2905.JPG
Date Stamp:	3/5/2024
Time Stamp:	12:05 PM
Description:	Conveyance at the downgradient end of the log storage area. Collected water is conveyed in the direction shown into the retention pond system.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2906.JPG
Date Stamp:	3/5/2024
Time Stamp:	12:05 PM
Description:	Additional view of the drainage channel shown in photo DSCN2905 by the log storage area. The site is graded such that runoff does not discharge offsite at the back of the property.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2907.JPG
Date Stamp:	3/5/2024
Time Stamp:	12:07 PM
Description:	500 gallon mobile diesel fuel tank, consistent with SPCC





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2908.JPG
Date Stamp:	3/5/2024
Time Stamp:	12:08 PM
Description:	Labels in the field correspond with the outfall numbers assigned in the SWPPP.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2909.JPG
Date Stamp:	3/5/2024
Time Stamp:	12:09 PM
Description:	View of the facility's diesel fuel tank and a nearby spill kit.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2910.JPG
Date Stamp:	3/5/2024
Time Stamp:	12:09 PM
Description:	Additional view of site and log storage area





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2911.JPG
Date Stamp:	3/5/2024
Time Stamp:	12:14 PM
Description:	Location where outfall 003 leaves the property.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2912.JPG
Date Stamp:	3/5/2024
Time Stamp:	12:14 PM
Description:	Looking upgradient at the channel for Outfall 003. The sides of the conveyance were beginning to erode and had some bare areas.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2913.JPG
Date Stamp:	3/5/2024
Time Stamp:	12:15 PM
Description:	The slopes behind the maintenance shed and above the conveyance for Outfall 003 (see photo DSCN2912) showed signs of erosion and rill formation.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2914.JPG
Date Stamp:	3/5/2024
Time Stamp:	12:21 PM
Description:	Click or tap here to enter text.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2915.JPG
Date Stamp:	3/5/2024
Time Stamp:	12:22 PM
Description:	See also photo DSCN2916. View of water discharging from the skimmer into the riser structure at pond 001. Outfall 001 is shown in photo DSCN2919.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2916.JPG
Date Stamp:	3/5/2024
Time Stamp:	12:22 PM
Description:	See also photo DSCN2915. The riser structure at pond 001 was equipped with a floating surface skimmer.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2917.JPG
Date Stamp:	3/5/2024
Time Stamp:	12:24 PM
Description:	Additional view of pond 001.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2918.JPG
Date Stamp:	3/5/2024
Time Stamp:	12:25 PM
Description:	Additional view of pond 001. The riser structure is visible in the center-left of the photo.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2919.JPG
Date Stamp:	3/5/2024
Time Stamp:	12:25 PM
Description:	View of outfall 001.





PHOTO LOG

Facility Name:	Amite BioEnergy (Drax)
EPA Division:	ECAD
EPA Group:	Water
EPA Media:	Stormwater - Industrial

Photo ID:	DSCN2920.JPG
Date Stamp:	3/5/2024
Time Stamp:	12:26 PM
Description:	Looking downgradient from outfall 001.

