

ABERDEEN PERSONNEL EXPOSURES TO VCM - NOT WEARING RESPIRATORS - 1975-1976Brewer, Jimmy

4/75 = 6.1

Yard operator, helping unload a VCM rail car.

Gates, Elmer

7/75 = 15.6

Warehouse worker, was moving fresh bagged resin from the vinyl bagging area into East Warehouse.

Harlow, Willis

11/75 = 5.98

Maintenance mechanic, working on D-600 gearbox.

Hawkins, Charles

4/76 = 2.34

Large reactor operator, changing VCM filters.

6/76 = 1.38

Large reactor operator, cause not known for sure.

Suspected exposed while changing of slurry transfer lines on blend tanks.

Johnson, Don

1/76 = 6.1

Large reactor operator, cause not given.

Morgan, Bob

4/76 = 2.0

Vinyl dryer utility, while working in V-11 Dryer Building.

Patterson, Randy

7/75 = 18.5

Warehouse worker, was moving fresh bagged resin and worked on shrink wrap operations.

Ray, Cecil

4/76 = 2.9

Transportation warehouse worker, while transferring fresh resin from the staging area to the East Warehouse.

5/76 = 1.66

Same reason.

Stanton, Tommy

7/75 = 20.6

Laboratory technician, beaker of liquid VCM was being boiled off for peroxide test in a malfunctioning lab hood.

Stone, Bud

4/76 = 1.31

Transportation warehouse worker, moving fresh resin from staging area to East Warehouse.

Trimble, Joe

4/76 = 1.67

Transportation warehouse worker, moving fresh resin from staging area to East Warehouse.

York, Charles

4/75 = 13.6

Development lab technician, VCM sample bomb valve leaked in laboratory.

Young, John

7/75 = 18.1

Warehouse worker, working on shrink wrap operations.

ABERDEEN PERSONNEL EXPOSURE TO VCM - 1975-1976

[illegible]



ABERDEEN PERSONNEL EXPOSURE TO VCM - 1975-1976

[illegible]