



INTERNAL
CORRESPONDENCE

PLAINTIFF'S EXHIBIT

UC-2704

UNION CARBIDE CORPORATION TECHNICAL CENTER
P.O. BOX 8361, SOUTH CHARLESTON, WV 25303

To (Name) H. E. Rucker
Division 512/2009
Location
Area

Date April 3, 1987

Originating Dept. EM&TS - HS&EA

Area Industrial Hygiene

Copy to B. H. Avashia, M.D. - 512/33
J. W. Barna - 2009/6
W. L. Browning - 2009
R. E. Coyner - 2009
T. L. Grittie - 380
C. P. Maxwell - 701/2
B. R. McMakin - 2009

Subject Asbestos Exposure Monitoring

Attached are the results of the asbestos exposure monitoring performed on construction employees by the site IH personnel at the Sistersville Plant. Employees were monitored over a three day period while repairing and covering asbestos insulation on the stills in the rectification area of the Sistersville Plant.

Employees were equipped with coveralls, boots, gloves, and head cover. In addition employees were supplied air respirator on the first day and HEPA cartridge equipped respirator for rest of the period during the repair work.

The monitoring results indicate that the exposure levels were well below the 0.1 fiber/cc Action Level standard established by OSHA.

Please inform the monitored employees of their exposure monitoring results as soon as possible. Also, have all monitored employees to sign and date this report and return to M. A. Patel, Building 701-330, Technical Center.

If you have questions, please feel free to call me at extension 3750.

Manhar A. Patel
Manhar A. Patel

Attachment
MAP:rab
2214P

UCC 024564

ASBESTOS EXPOSURE MONITORING

SISTERSVILLE PLANT

<u>Date</u>	<u>Sample Type Employee Name</u>	<u>Sampling Time - Min.</u>	<u>Air Conc. fibers/cc</u>	<u>TWAg fibers/cc</u>	<u>COMMENTS</u>
1-9-87	C. E. Rose	55	<0.02	-	Repairing/covering insulation on the stills in the Rectification area.
1-9-87	D. R. Samples	53	0.01	-	Repairing/covering insulation on the stills in the Rectification area.
1-12-87	J. C. Hubbard	201	0.002	-	Repairing/covering insulation on the stills in the Rectification area.
1-13-87	T. K. Miller	290	0.03	-	Repairing/covering insulation on the stills in the Rectification area.
1-13-87	J. A. Casto	294	0.04	-	Repairing/covering insulation on the stills in the Rectification area.

2214P

UCC 024565