

Region 6 - Enforcement & Compliance Assurance Division

INSPECTION REPORT

Inspection Date(s):	06/05/2025	
Media Program:	Water	
Regulatory Program(s)	Clean Water Act-National Pollution Discharge Elimination System (Brine)	
Company Name:	R&D Resources	
Facility Name:	Stoney #1	
Facility Physical Location:	Latitude: 36.695385, Longitude: -96.321745	
(city, state, zip code)	Pawhuska, OK, 74056	
Mailing address:	19407 E 126th St. N.	
(city, state, zip code)	Collinsville, OK, 74021	
County/Parish:	Osage County, OK	
Facility Phone Number	918-948-5475	
Facility Contact:	Devin Robinson	Owner
	robinsonoilfieldservices@gmail.com	
FRS Number:	n/a	
Identification/Permit Number:	OKU002217	
Media Identifier Number:	n/a	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Matthew Allen	EPA/Region 6 ECDW	Inspector
EPA Lead Inspector Signature/Date		
	Matthew Allen	Date
Supervisor Signature/Date		
	Jeanne Eckhart	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 Inspector, Matthew Allen, arrived at the R&D Resources, Stoney #1 Lease (EPA ID No. OKU002217) at 11:15 AM on 06/05/2025 for an announced follow-up inspection in response to a spill inspection conducted 5/29/2025. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with Environmental Protection Agency (EPA) regulations. There was no company representative present during the inspection. There was no federal, state, or local agency representative present at the time of the inspection.

FACILITY DESCRIPTION

EPA conducted an inspection at the R&D Resources, Stoney #1 Lease where runoff water from recent heavy rainfall was pumped into oil/saltwater holding tanks by an automatic sump pump, causing the tanks to overflow into the facility's secondary containment. The secondary containment was overfilled, which released oil and saltwater onto the road, eventually entering the nearby county road conveyance. At the time of the inspection, the company estimated approximately 1.5 barrels of oil was release from the facility.

Section II - OBSERVATIONS

I observed oil-stained soil and vegetation in the conveyance along the east side of Lynn Avenue, near the point of entry, see Photo No. 1. For additional GPS location information and photo metadata, please see Appendix 1 (photo log) attached to this report.

In the conveyance along the westside of Lynn Avenue, I observed significant oil-stained soil and vegetation, see Photo No.2.

Section III – AREAS OF CONCERN

The primary area of concern was the oil-stained soil and vegetation in the conveyance along Lynn Avenue.

Section IV – FOLLOW UP

EPA inspector conducted a follow-up call with the facility operator, Johnny Webb. Mr. Webb stated clean-up was still being completed and would continue until all impacts were corrected.

EPA inspector will conduct follow-up calls, field meetings and inspections to ensure the impacted area is returned to "pre-spill" condition.

Section V – LIST OF APPENDICES

Appendix 1 – Photo Log – 2 photos taken 6/05/2025.

Appendix 1

Photograph Log 2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.695385, -96.321745		
City: Pawhuska	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010687

Orientation: SSW

Date of Photo: 6/5/2025

Time of Photo: 11:19AM

Latitude: 36.695450

Longitude: -96.321773

Photographer: Matthew Allen

Description: Looking SSW, showing oil staining present on vegetation near the point of entry into the conveyance along Lynn Avenue.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.695385, -96.321745		
City: Pawhuska	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010688

Orientation: W

Date of Photo: 6/5/2025

Time of Photo: 11:20AM

Latitude: 36.695362

Longitude: -96.321930

Photographer: Matthew Allen

Description: Looking W, showing oil-stained soil and vegetation present in the conveyance along Lynn Avenue.