

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	10/17/2024	Time	08:00
		Operator Representative	Bandwheel Production Company, LLC		
Operator Info	Bandwheel Production Company, LLC P.O. Box 700426 Tulsa, OK 74170 Phone: 918-932-8418	Inventory ID	OS1014000		
		API Well No			
		Lease Name	Bandwheel		
		Well ID	13W7-3		
Location	NW 13 23N 08E	Status	Inactive	Well Type	Disposal
Latitude	36.475947	Longitude	-96.400674		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	Bandwheel Production Company		
Inspect No.		Date Last MIT	09/03/2009	Last Test Result	Fail
Casing	5.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 585
FLM Canister Pressure		Actual Pressure			Max Volume
Lease Status		Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed Lester Well Service run in well OS1014000 to 1850 feet below the land surface and tag the top of the bottom plug which was set on 10/16/2024. Lester Well Service pulled up hole to 950 feet below surface and spotted 20 sacks of class A cement, then pulled tubing from the hole. Elite Wireline shot the required 7 sets of perforations at 350', 300', 250', 200', 150', 100' and 50'. Lester Well Service ran back in to 350' below surface and circulated 140 sacks of cement to the surface. Inspector observed cement standing full 1 foot below the surface.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.475947, -96.400674		
City: Hominy	County/Parish: Osage	State: Oklahoma



Photo File Name: IMG_0058

Orientation: N

Date of Photo: 10/17/2024

Time of Photo: 3:12 PM

Latitude: 36.475947

Longitude: -96.400674

Photographer: Matthew Allen

Description: This was well OS1014000 with cement circulating to the surface.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.475947, -96.400674		
City: Hominy	County/Parish: Osage	State: Oklahoma



Photo File Name: IMG_0059

Orientation: N/A

Date of Photo: 10/17/2024

Time of Photo: 3:16 PM

Latitude: 36.475947

Longitude: -96.400674

Photographer: Matthew Allen

Description: This was well OS1014000 standing full of cement, 1 foot below surface with no fallback.