



Photographs for St. Marys Wastewater Treatment Lagoon

Inspection Type: Compliance Evaluation Inspection

Photo number 463 taken by **Privacy** on 8/22/2023.

The direction of the photo is West.

Description:

Overview of cell 2. Empty with exposed sludge.



Photo number 464 taken by **Privacy** on 8/22/2023.

The direction of the photo is South.

Description:

Overview of cell 3. Empty with vegetation growing inside cell.





Photographs for St. Marys Wastewater Treatment Lagoon

Inspection Type: Compliance Evaluation Inspection

Photo number 465 taken by **Privacy** on 8/22/2023.

The direction of the photo is North.

Description:

Overview of cell 1. Cell was very full and had cattails and algae inside.



Photo number 466 taken by **Privacy** on 8/22/2023.

The direction of the photo is Northeast.

Description:

No gate and missing fence at NE corner of cell 1.





Photographs for St. Marys Wastewater Treatment Lagoon

Inspection Type: Compliance Evaluation Inspection

Photo number 467 taken by **Privacy** on 8/22/2023.

The direction of the photo is East.

Description:

Lack of gate and faded sign at entrance to lagoon.

