

NOTICE: THIS MATERIAL MAY BE PRO-
TECTED BY COPYRIGHT LAW (PL94-553) OF
THE U.S. CODE.

A HEALTH SURVEY OF PIPE COVERING OPERATIONS IN CONSTRUCTING NAVAL VESSELS*

WALTER E. FLEISCHER,¹ FREDERICK J. VILES, JR.,² ROBERT L. GADE³ AND PHILIP DREXLER⁴

ed no significant or
exposed dogs and
normalities. The results
function did not indicate

the concentration of
blood of exposed rabbits
out.
at exposed rats, mice and
stance in the urine which
red color when the urine
avings.

DOCUMENTS

Dr. Charles Seegmiller for
distillation of samples
determining the indices
Elyn Peake and Mrs.
sted with the experiments.
out studies of pigment
els, as indicated above.

modification of Perl's
consideration in tissues. Arch.
10

W. L. L.: Supernatur-
es in dilute isopropanol
of acute fatty degeneration
Herzheimer technique. Arch.
11

Determination of volatile halo-
carbons in blood. THIS J., 25:

the physiological
trichlorethylene. THIS J., 26:

MACLEAN, D. C. AND CUN-
comparison of the toxicity
trichloroethylene and trichlorethylene.
10, 1938.

P. A. PERRY, T. L.
AND PORTERFIELD, V. T.
of 1,2-dichloroethane (ethylene
1. Its acute toxicity and the
agents. J. Pharmacol. &
4, 53, 1945.

H. F., JR., AND CARPENTER:
toxicity of carbon tetra-
al exposures and field studies.
77, 736.

W. F.: The halogenated hydro-
toxicity and potential dangers.
19, 237.

AN INDUSTRIAL health inspection of an
important U. S. Navy Contract Yard
indicated that dustiness from miscellaneous
pipe covering operations was considerable and that
a few of the employees had what appeared to be
asbestosis. This is a well-known industrial disease
caused by only one thing—prolonged breathing of
asbestos dust. The clinical manifestations are
shortness of breath and an unusual chest picture
by X-ray. In industry the disease is often dis-
abling, but it is much less frequent than silicosis,
with which it very properly is classed.

It was not felt that experience in a single yard
was enough to justify any general statements on
working conditions in other yards, and certainly
was no cause for alarm, but the results warranted
check-ups elsewhere. Accordingly, arrangements
were made to examine by chest X-ray the pipe
coverers in two Government Navy Yards, A and
B, and in two Navy Contract Yards, C and D.
Examinations were made of the working conditions
including dust counts of the air breathed with
microscopic and chemical analysis of the dust
itself.

We would point out that this procedure is
customary in making such surveys of occupational
diseases—medical examination of the workers
and a study of the nature and concentration of
the contaminants in the air breathed.

PIPE COVERING MATERIAL

An important ingredient of pipe covering
material used on U. S. Navy vessels is amosite.
This mineral is a magnesium iron silicate of
variable composition. The name is the generic
one for an asbestos type of fibrous mineral mined
in South Africa.

The chief reasons for the wide use of amosite

* Received for publication September 21, 1945.
Published by permission of the U. S. Navy. The opin-
ions and assertions contained herein are the private ones
of the writers, and are not to be construed as official or
reflecting the views of the Navy Department or the
naval service at large.

¹Comdr. MC. USNR, Asst. Chief Health Consultant

²Lieut. H(S) USNR, Health Consultant.

³Lieut. H(S) USNR, Health Consultant.

⁴Chief Health Consultant, U. S. Maritime Commis-
sion.

felt and pipe covering in naval work are its low
thermal conductivity, light weight, strength, and
refractoriness. When the felt and pipe covering
were first developed, we were still building vessels
under the Washington Treaty of Limitations in
Tonnage, and every pound saved meant that much
more armor, guns or ammunition for a given
displacement, to say nothing of more economic
operation for the weight involved in insulation.

Amosite pipe covering weighs about 14 pounds
per cubic foot, with a temperature limit of 750°F.
as compared to magnesia with a weight of 16
pounds per cubic foot, and a temperature limit of
500° F. High temperature amosite pipe covering
weighs about 18 pounds per cubic foot as compared
to 26 pounds per cubic foot for other high temper-
ature insulations. Because of the lower con-
ductivity and the higher temperature limit of
the amosite type, less of it need be used in a com-
bination covering than other types of insulations.

The development of amosite felt started in
1934 when a need existed to secure a thermal
insulation lighter in weight and thermally more
efficient than the materials (blocks and cement or
asbestos blankets) which were then being used
on destroyer turbines. The Navy approved the
type developed by a manufacturer in September,
1934. Originally amosite was used only for
turbine insulation, but it proved so satisfactory
that its field of application enlarged to include
insulation of valves, fittings, flanges, etc. From
the initial destroyer, it has been used on almost
all the destroyers built since that time and on
all other combat vessels built since before the
War.

Pipe covering was a later development in late
1935 and early 1936. Due to the manufacturing
problems involved, it took a longer time to evolve
into a satisfactory shape, and its first use on naval
vessels was in 1937. Since that time its use has
spread markedly and it was used on the great
majority of naval combat vessels built during
World War II.

Water-repellent amosite felt was developed
during the early part of 1942, as a replacement
for hair felt in the insulation of cold water lines
to prevent sweating. Hair felt had the disad-

PLAINTIFF'S EXHIBIT DOW-85	DEFT ARMSTRONG
	EXHIBIT NO. 2
	WORLDWIDE COURT REPORTERS

vantage of being combustible and as it was organic, when it became wet it moulded or rotted and could harbor vermin. At this time fires on board certain naval vessels convinced the Navy of the desirability of eliminating any combustible material from on board ship. Eventually water-repellent amosite was made in strips of 50 foot lengths and of suitable width to enclose the circumference of the pipe and enclosed in an extremely light-weight muslin to facilitate handling and reduce the dust, which the water-repellent agent accentuated.

I. DESCRIPTION OF OPERATIONS AND WORKING ENVIRONMENT

Asbestosis results from breathing asbestos fibers of relatively long length, such as 15 to 75 microns. It is not caused by breathing chopped up asbestos fibers of one or two microns (1). Therefore we are concerned with the presence in air of asbestos fibers which can be seen as such under low power of the ordinary microscope.

The clinical picture of asbestosis can easily be complicated by the presence of diatomaceous earth, a form of amorphous silica, which can cause silicosis and is probably a more serious health risk than asbestosis.

Another dust which may be present is magnesia, MgO , which is in very common use as a heat insulator and is harmless.

Therefore our analyses were done to indicate how much fibrous type of asbestos dust was present in the air breathed, how much silica was present (especially as diatomaceous earth), and how much of the harmless ingredients like iron oxide and carbonates.

Pipe covering may be divided into seven different operations as follows:

1. Laying out and cutting
2. Band saw cutting
3. Sewing and preparation of boots and jackets
4. Cement mixing
5. Molding
6. Grinding
7. Installation on board ship

1. Laying out and cutting

Rolls of the insulating felt are unwrapped and unrolled on a large layout table or on the floor of the shop. This material, with the exception of the type known as water repellent amosite, is then well wetted with a fine water spray. It

is marked into measured sections and cut with a rotary electric hand saw. The cut sections are rolled up and either used immediately or stacked in the storeroom.

Usually one to three workers are employed at this operation. During the handling, unwrapping and unrolling of the asbestos, considerable dust arises, but appears to settle readily. A very fine water spray should be used for wetting down the material as a high velocity spray stirs up dust. Once it is wetted the handling and cutting of the material causes little visible dust. All of the four yards surveyed wet down the insulating material described above.

One Navy Yard has an elaborate exhaust system for the layout table. The entire top of this table is covered with small perforations through which the air is exhausted. This table is sufficiently large that no more than two-thirds of the top is ever covered with material and room air is thereby exhausted through the other third. While no velocity or capacity measurements were made on this system, data presented later in the report indicate that this control measure had a marked effect in reducing the dust count.

2. Band saw cutting

A standard band saw such as is found in wood-working shops is used to cut insulation blocks and boards into desired shapes. This operation produces large amounts of air-borne dust, most of which settles slowly. Normally there is only one worker on this operation at any one time.

Inasmuch as this is a very dusty operation, the band saw should be enclosed in a room by itself and should be equipped with adequate local exhaust ventilation both above and below the saw table. Because of the mechanical difficulties in locating this exhaust properly, some of the dust will escape into the air and the operator should therefore wear an approved dust respirator.

3. Sewing and preparation of boots and jackets

In this operation jacket covers for valves and pipe joints are fabricated. The work consists of cutting asbestos cloth with shears, padding the jackets with insulating material, and sewing with wire or asbestos cord. These operations give rise to only slight amounts of visible dust, and exhaust ventilation and respiratory protection are neither required nor used. There is usually a large number of workers doing this operation in one large room.

4. Cement mixing

For protection of the insulation with cement or asbestos fibers, a small amount of water is added thoroughly agit. A small amount of water is added to a pail with a trowel when the asbestos mixing trough is used. Ordinary separate room of exhaust vent or both, although.

Petrographic indicate that the may be as high as 5. Molding

Molding is the operation to fit odd shapes. Form is made to insulated. Block sections glued to with asbestos and with asbestos insulation can be to be installed. Usually done in operation. Very operation and no protection is required.

6. Grinding

Several shipyard prefabricated sections of this material cement, all of dustiness. Normal intervals exposed, but the general room exhaust respirator worn by

7. Installation

There are a number of covering on wrapped and put and joints and fit with asbestos cord. Some prefabricated some hand sewed mixed cement is a smoother finish

and sections and cut with
The cut sections are
used immediately or stacked

Three workers are employed at
during the handling, unwrapping
asbestos, considerable dust
settle readily. A very fine
be used for wetting down the
velocity spray stirs up dust.
handling and cutting of the
visible dust. All of the
eyed wet down the insulating
above.

is an elaborate exhaust system
ble. The entire top of this table
small perforations through which
is. This table is sufficiently
than two-thirds of the top is
material and room air is thereby
the other third. While no
measurements were made
data presented later in the report
is control measure had a marked
dust count.

and saw such as is found in wood-
to cut insulation blocks and
shapes. This operation
amounts of air-borne dust, most
slowly. Normally there is only
operation at any one time.

is a very dusty operation,
should be enclosed in a room by
equipped with adequate local
at both above and below the
cause of the mechanical difficulties
is exhaust properly, some of the
the air and the operator should
approved dust respirator.

and preparation of boots and jackets
ration jacket covers for valves and
oriented. The work consists of
cloth with shears, padding the
insulating material, and sewing with
cord. These operations give
amounts of visible dust, and
lation and respiratory protection
required nor used. There is usually
of workers doing this operation
round
wiring

For protection and to give a neat appearance
the insulation on board ship is usually covered
with cement containing a high percentage of
asbestos fibers. In mixing, the proper amount
of water is added to the dry asbestos cement and
thoroughly agitated with a hoe. Occasionally
small amounts of asbestos cement are mixed in
a pail with a trowel. Considerable dust is raised
when the asbestos cement is dumped into the
mixing trough and during the early stages of
mixing. Ordinarily this process is done in a
separate room and only one operator is exposed.
The dustiness of this operation warrants the use
of exhaust ventilation or respiratory protection
or both, although neither is generally used.

Petrographic analyses of asbestos cement in-
dicate that the amount of diatomaceous earth
may be as high as 87 per cent by count.

5. Molding

Molding is the process of building up the insula-
tion to fit odd shapes of boilerwork and piping. A
form is made to the exact shape of the part to be
insulated. Block insulation is laid on, adjoining
sections glued together, exposed surfaces sealed
with asbestos cement and the whole mold covered
with asbestos cloth. When dry, the molded
insulation can be lifted off the form and is ready
to be installed on board ship. This operation is
usually done in the shop next to the sewing
operation. Very little dust is produced from this
operation and no special ventilation or respiratory
protection is required.

6. Grinding

Several shipyards reclaim their scrap pieces of
prefabricated sections of insulation by grinding
up this material and using it in the asbestos
cement, all of which contributes considerable
dustiness. Normally this job is done at infre-
quent intervals and only one or two men are
exposed, but the operation should be isolated,
general room exhaust supplied and an approved
respirator worn by the operator.

7. Installation of pipe covering on board ship

There are a number of operations involved in
pipe covering on board ship. Insulation felt is
wrapped and pounded tightly around large pipes
and joints and fastened firmly in place with wire
or asbestos cord. Pipes and boilers are covered
with prefabricated sections, which necessitates
some hand sewing to fit the sections. Ready
mixed cement is applied to fill in spaces and give
a smoother finish. Some insulation is wrapped

with glass cloth or asbestos cloth for greater
strength. The only operations that produce much
dust are the wrapping and pounding of amosite
and the sewing of sections.

Nearly all of the compartments on board ship
are involved in this work, although most of it is
concentrated in the machinery spaces. Usually
the greater number of pipe coverers work on board
ship and relatively few men in the shop. The
spacing of workers ranges from one or two men
doing a small job in a living space to as many
as twenty or thirty men working on ten or more
jobs in the engine room. Temporary exhaust
ventilation is seldom used on board ship for pipe
covering and very few of the workers wear respira-
tors.

Because of the varied nature of pipe covering
operations in ship compartments, general exhaust
ventilation is to be preferred. If the compartment
is large, such as the main engine room, five air
changes per hour are needed. In small com-
partments, such as living spaces, ten to fifteen
air changes per hour are required.

II. COMPOSITION OF MATERIALS USED

According to Navy Specification the rovings
of asbestos insulating felt (amosite) shall contain
not less than 95 per cent asbestos fiber of the
following composition:

Silica (SiO ₂) per cent minimum.....	47.5
Iron oxide (Fe ₂ O ₃) per cent maximum.....	45.0
Magnesium oxide (MgO) per cent minimum.....	6.0

Typical analysis of the two types of asbestos
fibers in general use are tabulated below:

	Chrysotile	Amosite
Silica (SiO ₂).....	39.05%.....	50.24%
Magnesia (MgO).....	40.07%.....	3.96%
Alumina (Al ₂ O ₃).....	3.67%.....	
Ferric oxide (Fe ₂ O ₃).....	2.41%.....	7.80%
Ferrous oxide (FeO).....		32.00%
Sodium oxide (Na ₂ O).....		2.12%
Combined water (H ₂ O).....	14.48%.....	3.00%

Therefore amosite alone will not comply with
Navy Specifications because of the low magnesia
content and must be mixed with chrysotile
asbestos to equal or exceed the 6.0 per cent mini-
mum value for magnesia. On the other hand,
chrysotile cannot be used alone because of its
silica content which is below the minimum 47.5
per cent specified by the Navy. The two types

of asbestos fibers must be mixed together in the proper proportions to satisfy the values set for magnesia and silica. The amounts of these materials used to form this mixture therefore would be 6-43 per cent chrysotile asbestos and 94-57 per cent amosite asbestos.

These two fibers differ mainly in their physical characteristics. Chrysotile is capable of being readily separated into very fine fibers with a soft silky feel, whereas amosite is harsher and requires more manipulation to fiberize it. One authority has stated that the chrysotile has the finest individual fibers, and amosite the coarsest. Be-

and sewing were done with a small amount of space for storage. Cross draft ventilation was provided by open windows on both sides of the room.

Work on board ship was not supplied with exhaust ventilation.

No asbestos workers were found wearing respirators.

U. S. Navy Yard B.

There were 50 men working in the shop and 700 men on board ship. The shop was divided into four main rooms: Layout, Sewing, Cement, and Storage and Band saw combined. With the

mixing were done at respirators were used procedures. At the fabrication of boots carried out. A small was done on board ship.

Material was cut in a room and the open respirator. The dust through a slot under a part of the dust gi-

There was no exhaust other than for the pipe covering operation walls and rafters of frequent intervals cleaner. Most pipe applied in the even

Contract Yard D.

There were 8 men working on board ship were done in two shops and jackets for pipe fabricated and surpl smaller shop the of and cutting of amc and fire felt. There in either shop nor fo on board ship. All (in a compartment on who wore an approx man who cut the t was no band saw cu-

TABLE 1
SUMMARY OF MATERIALS USED AT EACH YARD PER MONTH

	NAVY YARD A	NAVY YARD B	CONTRACT YARD C	CONTRACT YARD D
Amosite	58,200 sq. ft.	50,000 sq. ft.	40,000 sq. ft.	6,325 sq. ft.
Amosite (water-repellent)	—	15,000 sq. ft.	—	3,300 sq. ft.
Prefabricated sections (molded and block)	600 sq. ft. 39,900 linear ft.	1,200 sq. ft. 115,000 linear ft.	1,750 sq. ft. 18,800 linear ft.	15,700 linear ft.
Asbestos cloth	76,500 sq. ft.	106,600 sq. ft.	34,700 sq. ft.	40,000 sq. ft.
Metallic twine	—	150 lb.	—	—
Asbestos yarn	—	—	—	—
Asbestos paper	—	5,500 sq. ft.	4,000 sq. ft.	5,500 sq. ft.
Asbestos board	2,700 linear ft.	6,000 sq. ft.	150 sq. ft.	—
Asbestos cement	34,400 lb.	15,000 lb.	37,500 lb.	38,500 lb.

cause of this difference we may suspect a decided decrease in the number of respirable fibers (below 200 microns in length and 5 microns in diameter) whenever amosite is used in preference to chrysotile asbestos.

III. PIPE COVERING FACILITIES AT INDIVIDUAL SHIPYARDS

U. S. Navy Yard A.

There were 84 men working in the shop and 467 men on board ship. The shop was divided into two rooms, one of which was primarily for storage and occasional grinding and band saw cutting operations. The only mechanical exhaust ventilation in the shop was provided for the grinding, mixing and band saw cutting operations and was inadequate. In the other room layout, cutting

exception of the Cement Room, the doors between these were normally left open.

The work in the Sewing Room consisted mostly of fabricating and sewing valve boots and jackets. All the cement used on board ship was mixed in the Cement Room. There was no exhaust ventilation for either the Sewing or Cement Room. The band saw was equipped with a flexible exhaust tube above the table and an exhaust around the blade below the saw table. The layout table was equipped with exhaust ventilation as described above. There was no exhaust ventilation supplied on board ship for pipe covering and no workers were found wearing respirators.

Contract Yard C.

There were 51 men working in the shop and 100 men on board ship. Layout, cutting and cement

There are no estimates of dustiness in the Ureessen et al. (2) the asbestos textile particles of total dust for that industry. that the asbestos textile industries differ in textile plants specific jobs with for some years, with rotate between shop large ship compartment in dust exposure.

In contrast to coverer's materials

A small amount of draft ventilation was on both sides of the was not supplied with were found wearing res-

ing in the shop and 700 the shop was divided into out, Sewing, Cement, and combined. With the

CONTRACT YARD D	
1. sq. ft.	6,325 sq. ft.
2. sq. ft.	3,300 sq. ft.
3. ft.	15,700 linear ft.
4. ft.	40,000 sq. ft.
5. sq. ft.	5,300 sq. ft.
6. ft.	—
7. sq. ft.	—
8. sq. ft.	38,500 lb.

at Room, the doors between ft pen. Room consisted mostly ing valve boots and jackets m board ship was mixed i. There was no exhaust ven Sewing or Cement Room ipped with a flexible exhaust a: an exhaust around the ble. The layout tabl dust ventilation as describ e: dust ventilation supplie e covering and no worker operators.

ing in the shop and 12 cutting and cement

mixing were done at one end of the shop. Dust respirators were occasionally worn during these procedures. At the other end of the shop the fabrication of boots, jackets and molds were carried out. A small amount of such fabrication was done on board ship.

Material was cut with a band saw in a separate room and the operator wore an approved dust respirator. The dust from this saw was exhausted through a slot under the table which caught only a part of the dust given off above the table.

There was no exhaust ventilation in the shop, other than for the band saw, and none for the pipe covering operations on board ship. All floors, walls and rafters of the shop were cleaned at frequent intervals with an industrial vacuum cleaner. Most pipe covering on board ship was applied in the evening during the second shift.

Contract Yard D.

There were 8 men in the shop and 160 men working on board ship. Pipe covering operations were done in two shops. In the main one, boots and jackets for pipe valves and connections were fabricated and surplus material stored. In the smaller shop the operations consisted of layout and cutting of amosite, water repellent amosite and fire felt. There was no exhaust ventilation in either shop nor for the pipe covering operation on board ship. All the asbestos cement was mixed in a compartment on board ship. The only worker who wore an approved dust respirator was the man who cut the two types of amosite. There was no band saw cutting of asbestos in this yard.

IV. ANALYSES OF SETTLED DUST AND DUST COUNTS

There are no established figures for permissible or safe dustiness in pipe covering operations. Dreesen et al. (2) in their study of asbestosis in the asbestos textile industry suggested 5 million particles of total dust by impinger as a threshold for that industry. We should like to point out that the asbestos textile and asbestos pipe covering industries differ widely in their dust exposures. In textile plants workers usually continue at specific jobs with fairly constant dust exposures for some years, whereas the pipe coverer may rotate between shop and ship and from small to large ship compartments with a wide variation in dust exposure.

In contrast to the textile worker the pipe coverer's materials differ markedly in their as-

bestos content, ranging from 85 per cent magnesia (10-15% asbestos) to amosite (95% asbestos). When asbestos cements contain large amounts of diatomaceous earth there is a resultant silicosis hazard as indicated above.

In general we feel that dust counts below 5 million particles per cubic foot by Konimeter indicate good dust control.

Our figures in Table 2 were determined by the Konimeter and not with the impinger instrument. We used the Konimeter because it is light, easily portable and takes records which can be kept indefinitely. As is indicated in Table 3, the dustiest operations are band saw cutting, cement mixing, and installation on board ship.

V. MEDICAL FINDINGS

The incidence of asbestosis among pipe coverers as determined by chest X-ray is given in Table 4. The relation between years of exposure and per cent asbestosis is included in Table 5.

Due to frequent turnover of shipyard workers and the length of time required to X-ray a large number of workers, the number X-rayed may not equal the number of pipe coverers. At Contract Yard C X-rays were examined of men who had left the yard while at Navy Yard B a few pipe coverers were not X-rayed. At Navy Yard A the 48 X-rayed out of 551 were all older men working in the shop.

Some of these pipe coverers had had pre-shipyard experience in the asbestos industry, but the tables are based solely on shipyard exposure. At Contract Yard C, for example, the Asbestos Shop estimated that about one-third of their pipe coverers had worked with asbestos before coming to the yard.

The one case of advanced asbestosis at Contract Yard C had worked in the asbestos industry for 23 years before coming to work in the yard. At Contract Yard D the two cases of moderate asbestosis had worked 22 years and 30 years at pipe covering in their yard.

All of the X-ray films used in the above data were first read by roentgenologists of the Medical Department of the yard and then by one of the authors (W. E. F.). Dr. W. C. Dreesen, U. S. P. H. S., was kind enough to examine the three positive plates and he agreed on the diagnosis.

Since only three workers out of the 1074 X-rayed had asbestosis, and each of the three had been a pipe coverer for more than 20 years, it would

TABLE 2
ANALYSES OF SETTLED DUST AND AIR SAMPLES*

Jan. 1946

OPERATION	PER CENT LESS THAN 10 MICRONS BY COUNT	ASBESTOS (below 100 microns)	PER CENT LESS THAN 10 MICRONS BY COUNT								DUST COUNTS (MPPCF)*								PER CENT ASBESTOS (FAC%)
			Histomonas	Serpentine	Other fibers (cotton, silk, wool, etc.)	Iron scale (ferrous)	Calcium carbonate and oxides	Others	Number of samples	Total dust		ASBESTOS DUST							
										Range of counts	Average	Range of counts	Average						
Layout and cutting																			
Navy Yard A.....	95	16	6	12	6	24	26	10	2	3.5-	8.7	6.1	0.21-0.50	0.35	5.7-	6.0			
Navy Yard B.....	98	10	8	12	tr	40	18	12	7	1.6-	6.3	4.2	0.01-0.54	0.23	0.6-	7.9			
Contract Yard C.....	95	30	5	10	tr	26	14	15	4	17.1-	25.2	20.5	1.13-4.30	2.18	6.6-	19.3			
Contract Yard D.....	95	26	6	8	tr	29	21	10	5	6.3-	16.3	10.9	0.09-1.16	0.63	1.4-	8.7			
Cutting with band saw																			
Navy Yard A.....									2	11.0-	19.2	15.1	0.10-0.14	0.12	0.7-	0.9			
Navy Yard B.....	98	9	7	8	tr	48	16	12	2	32.4-	46.6	39.5	2.8-	3.2	3.0	6.5-	8.7		
Contract Yard C.....	98	9	63	2	tr	10	4	12	3	18.2-100+	73+		.9-12.8	6.19	4.3-	12.8			
Molding operations																			
Contract Yard C.....	98	8	66	3	tr	7	6	10											
Contract Yard D.....	95	4	9	7	tr	48	10	12											
Sewing & prep. of boots & jackets																			
Navy Yard A.....									2	3.5-	6.1	4.6	.01-	.06	0.03	0.3	-1.0		
Navy Yard B (Sewing asbestos cloth)	98	12	tr	9	tr	42	21	16	3	3.3-	6.0	6.8	0.0-	9.4	0.1	0.	-6.4		
(Stuffing with amosite)...	98	8	8	11	tr	38	20	15	1	2.1-		2.1	0.		0.3	0.			
Contract Yard C.....	95	26	6	11	3	25	12	14	2	10.6-	12.3	11.4	.45-	.79	.62	3.7	-7.4		
Contract Yard D.....	98	6	6	8	tr	38	28	14	5	3.9-	10.9	6.0	0.	-.05	.03	0.	-0.5		
Storeroom																			
Contract Yard D.....	95	15	8	7	tr	26	32	12											
Cement mixing																			
Navy Yard A.....									16	5.4-	30+	31+	0.	-0.52	0.2	0.	-0.7		
Navy Yard B.....									2	67.	-100+	84+	1.6	-1.7	1.7	1.4-	2.3		
Contract Yard C.....									2	33.8-	48.7	41.3	1.6	-1.7	3.1	4.7-	10.0		
Contract Yard D (on board ship).....									5	19.6-	40.0	32	0.	-.02	.01	0.	-.001		
Grinding scrap materials																			
Navy Yard A.....	88	8	20	16	1	10	33	12	15	9.4-100+	50+	0.	-1.6	.47	0.	-2.6			
General room																			
Navy Yard A.....									49	0.2-	24.6	10.0	0.	-1.4	0.08	.02-	0.3		
Navy Yard B.....									2	1.6-	3.3	2.4	0.	-.01	.01	0.	-0.6		
Contract Yard C.....									4	0.0-	21.6	14.2	0.34	-1.7	.8	3.8	-7.9		
Contract Yard D.....									5	3.9-	10.9	6.0	0.	-.05	.02	0.	-0.3		
Aboard ship																			
Navy Yard A.....									10	65.	-250.	142	0.	-0.17	0.02	0.	-0.6		
Navy Yard B.....									15	54.4-	192.0	128	1.36	-3.21	2.3	1.1	-3.7		
Contract Yard C.....									15	25.3-	89.0	49.2	0.23	-2.38	1.10	0.5	-6.8		
Contract Yard D.....									15	8.0-	22.1	11.0	0.	-0.21	0.03	0.	-1.6		

* Note: MPPCF = Million particles of dust per cubic foot of air.

Col

OPERATION

Layout and cutting...
Hand saw cutting....
Sewing and fabrication
Cement mixing.....
Grinding.....
General room.....

Shop average.....
Ship average.....

* Note: MPPCF =

INCIDENCE OF ASBE

SHIPYARD

Navy Yard A.....
Navy Yard B.....
Contract Yard C.....
Contract Yard D.....

Totals.....

RELATIONSHIP BETWEEN
INCIDENTS

SHIPYARD

Navy Yard A { Expt
After
Perf

Navy Yard B { Expt
After
Perf

Contract Yard C { E
T

Contract Yard D { E
T

TABLE 3

COMPARISON OF DUSTINESS OF VARIOUS OPERATIONS IN EACH SHIPYARD

OPERATION	NAVY YARD A		NAVY YARD B		CONTRACT YARD C		CONTRACT YARD D	
	Total dust	Asbestos dust	Total dust	Asbestos dust	Total dust	Asbestos dust	Total dust	Asbestos dust
	MPPCF		MPPCF		MPPCF		MPPCF	
Layout and cutting.....	6.1	0.35	4.2	0.23	20.5	2.18	10.9	0.63
Band saw cutting.....	15.1	0.12	39.5	3.0	73.0	6.19	—	—
Drawing and fabrication.....	4.8	0.03	4.8	0.1	11.4	0.62	6.0	0.03
Cement mixing.....	31.0	0.2	34.0	1.7	41.3	3.1	32.0	0.01
Grinding.....	50.0	0.47	—	—	—	—	—	—
General room.....	10.0	0.08	2.4	0.01	14.2	0.8	6.0	0.02
Shop average.....	30.0	0.25	26.9	1.0	32.0	2.6	7.6	0.23
Ship average.....	142.0	0.02	128.0	2.8	49.2	1.1	11.0	0.03

* Note: MPPCF = Million particles of dust per cubic foot of air.

TABLE 4

INCIDENCE OF ASBESTOSIS AMONG PIPE COVERERS

SHIPYARD	NUMBER OF PIPE COVERERS	NUMBER EXAMINED	NUMBER OF CASES OF ASBESTOSIS		
			Minimal	Medium	Advanced
Navy Yard A.....	551	43	0	0	0
Navy Yard B.....	750	662	0	0	0
Contract Yard C....	174	196	0	0	1
Contract Yard D....	168	168	0	2	0
Totals.....	1683	1074	0	2	1

appear that asbestos pipe covering of naval vessels is a relatively safe occupation. However, it must be remembered that these men rotated among the various operations of pipe covering and were not continually exposed to high concentrations of asbestos dust as found in band saw cutting and cement mixing. The suggestions made relative to exhaust ventilation and respiratory protection are therefore of value in maintaining this low incidence of asbestosis.

DISCUSSION

The extremely low incidence of asbestosis found, 0.29 per cent, or 3 cases out of 1074 pipe coverers, stands in marked contrast to the high dust concentration found in several of the pipe covering operations. As shown in Table 3, the total dust concentration for band saw cutting ranged from 15.1 to 73.0 million particles per cubic foot, for cement mixing from 31.0 to 34.0, and for installation on board ship, from 11.0 to 142.0. The solution of this apparent discrepancy lies in a characteristic peculiar to the pipe covering trade, that is lack of a necessity for specialization. In general, pipe coverers are capable of doing all of the operations described above, and the worker may be changed from one operation to another or to different jobs in the same type of operation without loss of efficiency and according to the demands of ship construction. It is therefore apparent that a pipe coverer's environment may change every few days or few weeks at the most with a constant fluctuation in the dust concentration which he breathes. Therefore, the figures given in Table 3 for shop average and ship average cannot give a composite picture of the asbestos

TABLE 5

RELATIONSHIP BETWEEN LENGTH OF EXPOSURE AND INCIDENCE OF ASBESTOSIS

SHIPYARD		YEARS IN PIPE COVERING INDUSTRY			
		0-2	3-5	6-10	10 plus
Navy Yard A	Exposed.....	26	13	8	3
	Affected.....	0	0	0	0
	Percentage.....	0%	0%	0%	0%
Navy Yard B	Exposed.....	227	425	67	—
	Affected.....	0	0	0	0
	Percentage.....	0%	0%	0%	0%
Contract Yard C	Exposed.....	0	105	45	117
	Affected.....	0	0	0	1
	Percentage.....	0%	0%	0%	6%
Contract Yard D	Exposed.....	25	112	2	5
	Affected.....	0	0	0	2
	Percentage.....	0%	0%	0%	40%

that a worker may breathe over a period of years. It is further apparent that to obtain such a picture, daily dust counts at each specific job in each ship compartment and in the shop together with the time spent on each job would have to be compiled separately for each worker. In this respect, asbestos pipe covering differs markedly from the asbestos textile industry where dust concentrations for an operation do not fluctuate widely and where a worker will usually remain at a specific job for some years.

A further factor in maintaining a low incidence of asbestosis is that in band saw cutting, grinding, and cement mixing only one or two men are involved and the work is usually done at infrequent intervals such as several times a week.

Finally, pipe coverers also apply glass wool, rock wool, magnesia, and other types of non-asbestos insulation, all of which decreases the amount of exposure to asbestos dust. It seems likely to us that if the pipe coverers studied had worked steadily at any of the above operations where the amount of asbestos dust in the air was consistently high, the incidence of asbestosis

among these workers would have been considerably greater. ~~It is further apparent that to obtain such a picture, daily dust counts at each specific job in each ship compartment and in the shop together with the time spent on each job would have to be compiled separately for each worker.~~

VI. CONCLUSIONS

1. The character of asbestos pipe covering industry on board naval vessels is such that conclusions drawn from other asbestos industries such as textiles, cannot be applied.

2. The operations of band saw cutting, grinding, cement mixing, and installation on board ship should be equipped with exhaust ventilation to keep the total dust concentration low.

3. The incidence of asbestosis among pipe coverers in the shipyards studied was low, 0.29 per cent or 3 cases out of 1074. In view of the nature of shipyard pipe covering work, this low incidence is not surprising.

4. Since each of the 3 cases of asbestosis had worked at asbestos pipe covering in shipyards for more than 20 years, it may be concluded that such pipe covering is not a dangerous occupation.

REFERENCES

- (1) LANZA, A. J.: Silicosis and asbestosis. Oxford University Press, New York, New York, 1938.
- (2) DEXTER, W. C. et al.: A study of asbestosis in the asbestos textile industry. Bull. No. 241, Public Health Service, U. S. Treasury Department, 1938.

- (3) FARMY, J. C.: Ships and aircraft of the United States Fleet. 2nd War Edition, 1944. Published by Ships and Aircraft, 1265 Broadway, New York, New York.

EXPOSURES TO

Section of Industrial and Ad-

WELDING operations in construction often produce a plates upon cooling. It is prevalent on decks or surfaces are affected. measures include shrinkage application of heat, ordinary flame, to a distorted section or accompanied by a wat

Shrinkage is often necessary in confined spaces where the operation may cause measures are in use. An recently provided an exposure shrinker developing symptoms of nitrogen poisoning which 10 days later from report. Three other workers at exposure experienced a few symptoms, but were asymptomatic following day.

The purpose of this investigation was to determine the exposures which are small, unventilated compa

OPERATION

The torch ordinarily used in the conventional oxyacetylene welding is in most instances the acetylene ring attachment which supplies a continuous flow of water around the flame of the torch. When the steel plate can be restored with oxyacetylene welding the tip of the torch is directed on thin steel the flame is commonly used to cause the shrinking

* Received for publication
Industrial Hygiene En