

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	08/16/2022	Time	13:38
Inspection Due	2020-07-30T00:00:00Z	Operator Representative	John P. Long, Jr.		
Operator Info	John P. Long, Jr. 2200 McKenzie Rd. Pawhuska, OK 74056 Phone: 918-625-7282	Inventory ID	OS5470023		
		API Well No			
		Lease Name	Labadie		
		Well ID	12		
Location	SW 31 27N 11E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.770318	Longitude	-96.161764		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	John P. Long, Jr.		
Inspect No.		Date Last MIT	03/07/2012	Last Test Result	Acceptable
Casing		Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 645
FLM Canister Pressure		Actual Pressure			Max Volume 0
Lease Status		Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	At the time of the inspection, well OS5470023 (Labadie No. 12) was not connected or injecting. The valves and fittings on the well at the time of the inspection prevented observation of tubing and annulus pressures. At the time of the inspection, well fittings prevented observance of the tubing fluid level. The primary area of concern was the lack of accessible fittings to obtain well pressures and fluid level. The operator should equip the well with accessible fittings to accommodate measuring pressure on the tubing as well as the annulus. The well construction should also provide access to obtain fluid level measurements by use of an Echometer. The well sign should be updated. There were no other areas of concern at the time of the inspection.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.770318, -96.161764		
City: Okesa	County/Parish: Osage	State: Oklahoma



Photo File Name: DSCN0683

Orientation: E

Date of Photo: 8/16/2022

Time of Photo: 1:38 PM

Latitude: 36.770318

Longitude: -96.161764

Photographer: Jeanne Eckhart

Description: This was well OS5470023 (Labadie No. 12). The tubing should be equipped with a valve and female fitting to allow pressure readings to be taken. At the time of the inspection, if the tubing valve was open, air/gas would vent through the hose into the atmosphere and prevent observance of pressure on the tubing.