

FRICITION MATERIALS STANDARDS INSTITUTE, 588 MONROE TURNPIKE, MONROE, CT 06468
A U T O M O T I V E D A T A B O O K B U L L E T I N #5-971
May 12, 1998

This is the last Automotive Data Book Bulletin before copy was sent to the printer for the 1998 Automotive Data Book.

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>ACURA</u>			
1998, SLX	7585-D579**	D/D	7586-D580**
<u>CHRYSLER</u>			
1998, Concorde	7623-D730**	D/	
	(Note #1)		
1998, LHS	7623-D730**	D/	
<u>DODGE</u>			
1998, Intrepid	7623-D730**	D/	
<u>DODGE TRUCK (See Comments)</u>			
1998, Durango		/BH	2182TT-S734 (Note #2)
<u>FORD</u>			
1998, Crown Victoria		/D	7565A-D690
1998, Crown Victoria Police	7617-D748**	D/D	7555-D674**
<u>HYUNDAI</u>			
1998, Accent	7376-D497**	D/N	1379-S707*
1998, Elantra	7329-D700**	D/N	1495-S715*
	OR	/D	7344-D464**
1998, Tiburon	7329-D747**	D/N	1495-S715*
	OR	/D	7344-D464**
<u>INFINITI</u>			
1998, QX4	7566-D691**	D/N	1433-S631*
<u>ISUZU</u>			
1998, Amigo	7585-D579**	D/D	7586-D580**
<u>LAND ROVER</u>			
1998, Range Rover	7556-D676**	D/	
<u>LINCOLN (See Corrections)</u>			
1998, Continental	7476-D598**	D/D	7489A-D610
1998, Mark VIII		/D	7477-D708**

SEE DISCLAIMER AT END OF BULLETIN

FMSI® and FMS® are registered trademarks of the Friction Materials Standards Institute, Inc.

Copyright© by Friction Materials Standards Institute, Inc.

	FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>MERCEDES</u>			
1998, C230	7523-D645**	D/D	7608-D739**
1998, C280	7583-D710**	D/	
1998, S320	7564-D689**	D/D	7526-D603**
1998, S420	7564-D689**	D/D	7484-D603**
1998, S500	7564-D689**	D/D	7484-D603**
1998, S600	7564-D689**	D/D	7484-D603**
1998, CLK320		/D	7526-D603**
1998, CL500	7564-D689**	D/D	7484-D603**
1998, CL600	7564-D689**	D/D	7484-D603**
1998, SLK230	7583-D710**	D/	
1998, SL500	7525-D561**	D/D	7484-D603**
1998, SL600	7525-D561**	D/D	7484-D603**
1997, C280	7583-D710**	D/D	7496-D620**
	OR	/D	7374-D495**
1997, C36	7583-D710**	D/D	7496-D620**
	OR	/D	7374-D495**
1997, S320	7457-D577**	D/D	7526-D603**
	OR	D/	
1997, S420	7457-D577**	D/D	7484-D603**
	OR	D/	
1997, S500	7457-D577**	D/D	7484-D603**
	OR	D/	
1997, S600	7457-D577**	D/D	7484-D603**
	OR	D/	
<u>MERCURY</u>			
1998, Grand Marquis		/D	7565A-D690
1998, Grand Marquis Police	7617-D748**	D/D	7555-D674**
<u>SAAB</u>			
1998, 9000	7292-D403**	D/D	7221-D322**
<u>SUBARU</u>			
1998, Forester	7589-D721**	D/N	1462-S676*
1998, Legacy	7590-D722**	D/N	1462-S676*
	OR	D/D	7351-D471**
<u>TOYOTA</u>			
1998, Corolla	7441-D562**	D/	
1998, Tercel	7153-D242**	D/N	1439-S642*
1998, T100 1/2T 4WD	7485-D686**	D/N	1397-589*
<u>VOLKSWAGEN</u>			
1998, Cabriolet	7578-D704**	D/N	1450-S662
1998, Golf	7569-D694**	D/N	1450-S662
	OR	D/D	7234-D340**
	OR	D/	
1998, Jetta	7569-D694**	D/N	1450-S662
	OR	D/D	7234-D340**
	OR	D/	

May 12, 1998

COMMENTSExisting lining used with new shoe:

<u>Lining</u>	<u>Assembly</u>	<u>Application</u>
2182TT	2182TT-S734	1998 Dodge Durango Rear

Existing shoe with new lining:

<u>Shoe</u>	<u>Assembly</u>	<u>Application</u>
D730	7623-D730	1998 Chrysler Concorde Front
		1998 Chrysler LHS Front
		1998 Dodge Intrepid Front

CORRECTIONS

Bulletin #4-971 listed 1998 Lincoln Mark VIII rear as 7477A-D599. The correct listing is 7477-D708.

DISC BRAKE LINING ASSIGNMENTS

Note #1

<u>FMSI 7623</u>	<u>7623-D730</u>
45.1 x 17.0 x 128.5	2 IM
40.2 x 14.9 x 148.7	2
(1.78 x .670 x 5.06)	
(1.58 x .587 x 5.85)	

DRUM BRAKE SHOE ASSIGNMENTS

Note #2


<u>FMS S734</u>	<u>2182TT-S734</u>
11.03 x 2.25	Dodge Truck

The data shown in this bulletin has been supplied by sources considered to be reliable. While we believe that such information is correct, the Institute cannot and does not accept any responsibility or liability for errors or omissions, or harm resulting therefrom.

The data shown in this bulletin indicates dimensions only and in no way refers to the quality of any materials that may be embodied in the product or particular application involved, and moreover, SINCE FIELD CONDITIONS AND OTHER FACTS MAY NECESSARILY VARY FROM ONE APPLICATION TO ANOTHER, FRICTION MATERIALS SUPPLIERS AND INSTALLERS SHOULD RELY ULTIMATELY AND SOLELY UPON THEIR OWN EXPERTISE AND JUDGMENT AS TO QUALITY AND DIMENSIONAL SIZE. Under no circumstances should replacement items be used when they do not appear to fit, nor be "forced" to fit, nor be modified in the field instead of obtaining a properly sized item from a supplier. If such items are modified in the field to fit, the Institute specifically disclaims all liability and responsibility for any harm resulting therefrom.

If any error or omission is noted in this bulletin, it should be reported immediately to the Friction Materials Standards Institute, Inc., 588 Monroe Turnpike, Monroe, Connecticut 06468.

DISC BRAKE "D" NUMBERS



DRUM BRAKE SHOE NUMBERS

