

Inspection Report
Mechanical Integrity Test
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas TX 75270

Inspector Matthew Allen		MIT Date 06/26/2024		Time 11:00	
Operator Representative Performance Energy Resources, LLC		Report Sent Operator			
Inject Interval 2193 - 2990		USDW 380		Well Type Disposal	
Annulus Fluid Type Water		Concentric Pkr		Packer Depth 2134	
Casing 5.5		Tubing 3.5			
Operator Info Performance Energy Resources, LLC P.O. Box 628 Barnsdall, OK 74002 Phone: 918-847-2531			Inventory ID OS6337000		
			API Well No		
			Lease Name Howell		
			Well ID 11-8W		
			Location SE 08 25N 11E		
Type of MIT Casing - Tubing Annulus Pressure			Test Reason Routine		
Injecting N		Injection Rate (bpd)		Tubular Lining	
MIT Due 05/12/2023		MIT Freq EVERY THREE YEARS		Ann Filled (hrs)	
				Ann Press Mont	
Time		Tubing Pressure	Annulus Pressure	Flowback	Pressure
					Volume
Pre-Test		0	0	High	200
Initial 11:00		0	200	Mid	100
Mid 11:15		0	200	Low	20
Final 11:30		0	200	End	0
				Total Volume	3900
			ADA Pressure Test - Required Test Pressure		
			(Fluid Column Ht * Specific Gravity * .433 / N2 Wt Fac = Required Test Pressure)		
Fluid Migration Test Type		Remedial Action Type			
Inspection Comments		MIT conducted, pressure hold OK.			
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.657828, -96.13915		
City: Barnsdall	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010453

Orientation: ESE

Date of Photo: 6/26/2024

Time of Photo: 10:59 AM

Latitude: 36.657828

Longitude: -96.13915

Photographer: Matthew Allen

Description: This was the well sign for well OS6337000.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.657828, -96.13915		
City: Barnsdall	County/Parish: Osage	State: Oklahoma




Photo File Name: R0010454

Orientation: WSW

Date of Photo: 6/26/2024

Time of Photo: 11:00AM

Latitude: 36.683715

Longitude: -96.08638

Photographer: Matthew Allen

Description: This was well OS6337000 at the time of the inspection. The well was connected but not injecting.