



Photographs for Shell Valley Wasterwater Treatment Lagoons

Inspection Type: Compliance Evaluation Inspection

Photo number 502 taken by Akash Johnson on 8/23/2023. The direction of the photo is Southeast.

Description:

Overview of Cell 1. Cattails were growing along the interior of the berm.



Photo number 503 taken by Akash Johnson on 8/23/2023.

The direction of the photo is Northwest.

Description:

Overview of Cell 2. What was presumed to be transfer piping to Cell 3 is visible in the background (northwest corner of the cell); the transfer piping was elevated several feet above the surface of the water. Cattails were growing along the interior of the berm.





Photographs for Shell Valley Wasterwater Treatment Lagoons

Inspection Type: Compliance Evaluation Inspection

Photo number 504 taken by Akash Johnson on 8/23/2023.

The direction of the photo is Northwest.

Description:

Overview of Cell 3. Little water appeared to be in this cell. Cattails were growing throughout the interior of the cell.



Photo number 505 taken by Akash Johnson on 8/23/2023.

The direction of the photo is Southwest.

Description:

Overview of Cell 4. No water appeared to be in this cell. Cattails were growing along the interior of the berm and vegetation was growing throughout the interior of the cell.

