

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	10/16/2025	Time	11:30
		Operator Representative	Contango Resources, LLC		
Operator Info	Contango Resources, LLC 1717 South Boulder, Suite 900 Tulsa, OK 74119 Phone: 918-392-3396	Inventory ID	OS2836000		
		API Well No			
		Lease Name	NRU		
		Well ID	4W6		
Location	SE 09 24N 07E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.567642	Longitude	-96.551732		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	Contango Resources, LLC		
Inspect No.		Date Last MIT	12/15/2015	Last Test Result	Fail
Casing	5.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device FLM Canister Pressure Lease Status		Fittings	N	N	Max Pressure 680
		Actual Pressure			Max Volume
		Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed the surface restoration for well OS2836000. Areas of concern from the previous inspection on 9/22/2025 were fully addressed. There were no areas of concern at the time of the inspection.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.567642, -96.551732		
City: Fairfax	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010765

Orientation: SSW

Date of Photo: 10/16/2025

Time of Photo: 11:33AM

Latitude: 36.567642

Longitude: -96.551732

Photographer: Matthew Allen

Description: This was the location of well OS2836000, surface restoration was complete.