

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	03/25/2026	Time	08:30
		Operator Representative	McCann Resources, Inc		
Operator Info	McCann Resources, Inc 1613 West 6th Street Bartlesville, OK 740033404 Phone: 918-337-4747	Inventory ID	OS2222000		
		API Well No			
		Lease Name			
		Well ID	W-83		
Location	SE 16 27N 12E	Status	Active	Well Type	Enhanced Recovery
Latitude	36.812598	Longitude	-96.00877		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	McCann Resources, Inc		
Inspect No.		Date Last MIT	05/22/2018	Last Test Result	Acceptable
Casing	4	Tubing	1.0625	USDW	132
Monitoring Device Elected	N	Tubings		Annulus	
Monitoring Device FLM Canister Pressure		Fittings	N	N	Max Pressure 203
Lease Status	Active	Actual Pressure			Max Volume
Barrel Monitor Hooked Up?	N	Determined?			Max Inj Units Barrels Per Month
Barrel Fluid Level (%)		Static Fluid Level			
Flowline Hooked Up?	N	Determined?			
Injecting	N	Injection Rate (bpd)			
Inspection Comments	Well, OS2222000 appeared to be 4" casing with 2 1/16" tubing cemented to surface. The well was reduced to a 1" ball valve. Well fittings were tight and prevented observance of fluid level and pressure readings. The well was disconnected and not injecting. The well was overdue for MIT at the time of the inspection.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.812598, -96.00877		
City: Bartlesville	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010835

Orientation: W

Date of Photo: 03/25/2026

Time of Photo: 8:31AM

Latitude: 36.812598

Longitude: -96.00877

Photographer: Matthew Allen

Description: This was well OS2222000 at the time of the inspection. At the time of the inspection, the well was disconnected and was not injecting. The well was overdue for MIT.