

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	01/18/2023	Time	10:45
Inspection Due		Operator Representative	CapturePoint, LLC (formerly Perdure Petroleum, LLC)		
Operator Info	CapturePoint, LLC (formerly Perdure Petroleum, LLC) 1101 Central Expwy S., Suite 150 Allen, TX 75013 Phone: 832-300-8221	Inventory ID	OS6273134		
		API Well No			
		Lease Name	NBU		
		Well ID	22-03		
Location	NE 15 27N 05E	Status	Proposed Injection Well	Well Type	Enhanced Recovery
Latitude	36.8228	Longitude	-96.75143		
Inspection Reason	MIT	Responsible Company at Time of Inspection	CapturePoint, LLC		
Inspect No.		Date Last MIT		Last Test Result	
Casing	4	Tubing	2.0625	USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 2165
FLM Canister Pressure		Actual Pressure	100	0	Max Volume 186000
Lease Status	Active	Determined?	Company Gage	Open Value	Max Inj Units MCF per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	Y	Injection Rate (bpd)			
Injecting	Y				
Inspection Comments	Inspector witnessed Standard Annulus Pressure Test (SAPT) on well OS6273134. Pressure, hold OK. I observed no areas of concern at the time of the inspection. EPA enforcement staff will review inspection data to determine compliance with EPA UIC regulations. Initial: 315psi Mid: 315psi Final: 410psi Pressure Hold OK Total flowback: 4100ml				
Inspector Signature	MATTHEW ALLEN Digitally signed by MATTHEW ALLEN Date: 2023.01.30 12:37:27 -06'00'				
Supervisor Signature	JEANNE ECKHART Digitally signed by JEANNE ECKHART Date: 2023.01.30 12:48:31 -06'00'				

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.82287, -96.75139		
City: Shidler	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010043

Orientation: WNW

Date of Photo: 01/18/2023

Time of Photo: 10:53 AM

Latitude: 36.82287

Longitude: -96.75139

Photographer: Matthew Allen

Description: This was well OS6273134 at the time of inspection.