

Wastewater in Ethylene Oxide Service

- 40 CFR 63.101 (definition of "in ethylene oxide service")
- 40 CFR 63.104(k)

Monitoring of Equipment in Ethylene Oxide Service

- 40 CFR 63.119(a)(7)
- 40 CFR 63.168(b)(2)(iv) and (d)(5)
- 40 CFR 63.174

Fenceline Monitoring

- 40 CFR 63.184

Elimination of Delay of Repair

- 40 CFR 63.104(g)(6) and (h)(6)
- 40 CFR 63.174(a)(3), (b)(3)(vi), and (g)(3)
- 40 CFR 63.171(f)
- 40 CFR 63.168(b)(2)(iv) and (d)(5)
- 40 CFR 63.163(a)(1)(iii), (b)(2)(iv), (c)(4), and (e)(7)

Elimination of TRE

- 40 CFR 63.113(a)(4)

- *Facility(ies) and/or affected source(s)*

The affected facility is:
Indorama Ventures Oxides LLC
6001 Highway 366
RN100219252

This facility is subject to Title V Permit number 1320; Title V Permit O-2287; Title V Permit O-2288; Title V Permit O-3056; New Source Review ("NSR") Permit 106169; NSR Permit 29516; NSR Permit 5952A; NSR Permit 5972A; NSR Permit 5807A; NSR Permit 36646; and NSR Permit 20160, issued by the Texas Commission on Environmental Quality.

- *Length of compliance period being requested.*

Indorama requests a two-year extension of the applicable standards and limitations, subject to renewal by the President, as provided by 42 U.S.C. § 7412(i)(4).