

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424					Inspection ID	EPA Well ID#: F L S 1 1 3 0 0 8 1 Year-Month-Day: 2 0 2 4 - 0 5 - 0 1 EPA Permit # (or RA): F L I 0 0 5 3 Page 1 Of 2																
Inspector(s): Carol Chen (lead), Carla Foy Start Time: 11:57 am End Time: 12:01 pm																						
Facility Contact Information	Facility Name: Maverick Natural Resources, LLC (Breitburn Operating LP)																					
	Street Address: 5415 Oil Plant Rd																					
	City: Jay County: Santa Rosa State: FL Zip: 32565																					
	Nature of Business: oil and gas production																					
	Facility Owner/Operator: Maverick Natural Resources, LLC Phone: 850-675-1702																					
	Email:																					
	Facility Contact (if different): Al Jones, Plant Superintendent Phone: 251-227-3319																					
Well Data from File	O/O Mailing Address: 5415 Oil Plant Rd																					
	City: Jay County: Santa Rosa State: FL Zip: 32565																					
	Well Name & #: Braxton #21-1 API No. 0911320033																					
	Well Type (see table): Enhanced Oil Recovery (EOR) State Permit: OG_510																					
	Latitude (°N): 30.93770471 Longitude (°W): -87.17526027 Elevation (ft):																					
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing ☐ Other: surface casing 9 5/8" @3829'																					
	Total Depth (ft): 16084' Inner Casing Size (in): 7" @16082' Tubing Size (in): 3 1/2" @15550 Packer Depth (ft): Inj. Zone: ☐ Open Hole; ☒ Perforated; Top(ft) 1569 Bottom(ft): 15728 Max. Injection Pressure (psig): 7,260 PW/N ²																					
Field Measurements and Observations	Latitude (°N): No GPS 000 Longitude (°W): No GPS 000 Elevation (ft):																					
	EPA GPS ID: SC8284 Well Status (see table): TA If not Active, Reported Date Last Active: 2/11/22																					
	Nature of Injected Fluid(s) if any: Plug Set @ 15,536'																					
	General Condition of the Well Site:																					
	Notes & Comments (include discrepancies from database values):																					
	The injection well has been disconnected from the																					
	produced waters injection line. Pooling fluids are																					
	seen around the injection well. Repairs are planned																					
	in the future.																					
	Tubing Gauge: 0 psi																					
Production Gauge: 0 psi																						
Surface Gauge: 0 psi																						
Flow Line Gauge:																						
See reverse for additional observations, comments and photo log																						
UIC Inspector																						
Name: Carol Chen																						
Signature: CAROL CHEN Digitally signed by CAROL CHEN Date: 2024.06.20 21:56:53 -04'00'																						
UIC Inspector																						
Name:																						
Signature:																						

Version 2018-04-18

Inspection ID	EPA Well ID#:	F	L	S	1	1	3	0	0	8	1
	Year-Month-Day:	2	0	2	4	-	0	5	-	0	1
	EPA Permit # (or RA):	F	L	I	0	0	5	3			
					Page	2		Of	2		

[illegible]

Photographer: Carol Chen EPA Camera ID: SC8284

Photo ID: DSCN1418 Time: 11:57 am Lat (°N): No GPS 000 Long (°W): No GPS 000

Description: produced waters manifold, identification sign for the injection well

Photo ID: DSCN1419 Time: 11:58 am Lat (°N): No GPS 000 Long (°W): No GPS 000

Description: produced waters manifold

Photo ID: DSCN1420 Time: 12:00 pm Lat (°N): No GPS 000 Long (°W): No GPS 000

Description: back of injection well, disconnected from the injection line, pooling fluids all around

Photo ID: DSCN1421 Time: 12:00 pm Lat (°N): No GPS 000 Long (°W): No GPS 000

Description: front of injection well, showing gauge readings on tubing, surface and production casings

Photo ID: DSCN1422 Time: 12:01 pm Lat (°N): No GPS 000 Long (°W): No GPS 000

Description: close-up of surface and production gauges, reading 0 psi

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W): _____

Description: _____

UIC Inspector

Name: _____

Signature: _____