

FILE NAME: Reynolds Metals (RM)

DATE: 1989 Aug 31

DOC#: RM035

DOCUMENT DESCRIPTION: Sherwin Plant Safety Committee Meeting Minutes

Stan on Vacation

SHERWIN PLANT SAFETY COMMITTEE MEETING

August 31, 1989

PLAINTIFF'S
EXHIBIT

OLD BUSINESS

1. - Complete ^{of} 1. - Fac. 34 drainage problems and ditch near switch house; also missing grating south of #2 sump pump
- ~~1) should not be on~~ 2. - Janitorial service not up to our standards - none at all on weekends
- ~~3) - That with pool~~ 3. - Secondary tanks are running over while people are working in and around some. It has been agreed upon to put overflow or high level alarms on them to warn the people underneath to get clear. Help is being needed to get these installed as soon as possible.
- ~~4) NO!~~ 4. - 35 filter floor needs extensive scaling and clean up. My recommendation is to possibly get water jet people to go in and do the job.
5. More need in valve replacement due to leaky valves and valves not operating properly.

NEW BUSINESS

1. - People are running over hoses with scooters and trucks. This causes hoses to jump and buck. Hoses should be flagged off or boarded for truck crossings. Bottom of 45 area
2. Toggles or switch type should not be used to tag anything out except for breakers. ~~ON IS switches~~ most 110V circuits
3. Check secondary Teed lines for wall thickness. Top side 45
4. Asbestos on 35 filter floor - personnel was asked to remove some and when they informed the Foreman that wasn't the way asbestos was to be removed - Foreman preceeded to take a hammer and wedge and removed some, exposing all personnel on filter floor to asbestos all night. Fans installed in filter building was blowing asbestos all night. Steps should be made to prevent this from happening again. Next morning an asbestos removal crew was brought in.
5. Lighting on seed charge manifold - Area 45 topside
6. Turbo vents need to be installed on garage building. Also the back of the garage is being used as a thoroughfare.
7. #4 and #2 I.D. fanhas insulation hanging from them needs removing and replaced.
8. The new shaker screens removing oxalate from high tanks are dumping into dumpsters making a mess when these dumpsters are dumped. This is spilling caustic on the concrete pad in and around the Maintenance parts & storage shacks.

001042

* Stan - look into ^{10-15 min} ~~colfilm~~ on procedures to handle asbestos, that can be shown during monthly safety meetings.