




Region 6 Compliance Assurance and Enforcement Division
INSPECTION REPORT

Inspection Date(s):	10/19/2017		
Media:	Water		
Regulatory Program(s)	NPDES		
Company Name:			
Facility Name:	[REDACTED]		
Facility Physical Location:	[REDACTED]		
(city, state, zip code)	Loranger, LA 70446		
Mailing address:	[REDACTED]		
(city, state, zip code)	Loranger, LA 70446		
County/Parish:	Tangipahoa		
Facility Contact:	[REDACTED]	Owner	
FRS Number:	N/A		
Identification/Permit Number:	LAU000478		
Media Number:	N/A		
NAICS:	0241		
SIC:	112120		
Personnel participating in inspection:			
[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
Collin Martin	6EN-WC	Inspector	214-665-8380
Eura Dehart	LDEQ	Inspector	285-219-3030
EPA Lead Inspector Signature/Date	COLLIN MARTIN Digitally signed by COLLIN MARTIN DN: c=US, o=U.S. Government, ou=USEPA, ou=Staff, cn=COLLIN MARTIN, dnQualifier=0000082180 Date: 2017.12.07 11:09:27 -06'00'		
	{Inspector name}		Date
Supervisor Signature/Date	 Esteban Heron		12/7/17
	{Supervisor name}		Date

[REDACTED]
Inspection Date: 10/19/2017**Section I – INTRODUCTION****PURPOSE OF THE INSPECTION**

EPA Region 6 inspector Collin Martin and LDEQ inspector Don Weinell arrived at the [REDACTED] at 11:50 A.M. on 10/17/2017 for an unannounced inspection. The inspectors were not able to make contact with a representative of the facility. EPA Region 6 inspector Collin Martin and LDEQ inspector Eura Dehart returned to [REDACTED] at 1:02 P.M. on 10/19/2017. We met with [REDACTED] at the Opening Conference. I presented my credentials to [REDACTED] and informed him that this was an EPA inspection to determine facility compliance with the Clean Water Act. The scope of the inspection is a Compliance Evaluation Inspection.

FACILITY DESCRIPTION

[REDACTED] is an unpermitted facility that has approximately 138 cattle. At the time of the inspection, according to [REDACTED], the facility was milking 48 cows. In addition to the milking cows, [REDACTED] notified us that there were approximately 70 head of dry cows on site, 10 calves, and ten heifers. The cows are milked twice per day and between sessions kept in pasture.

Section II – OBSERVATIONSCoordination with NRCS:

[REDACTED] informed us that he has had no coordination with NRCS.

Retention Control Structure (RCS):

We observed the RCS to be in good condition and free from any evidence of discharge.

Land Application Areas:

At the time of the inspection, [REDACTED] informed us that he had approximately 111 acres to which he could apply wastewater liquids and solids.

Dewatering Equipment:

At the time of the inspection, [REDACTED] had a functioning electric pump capable of dewatering the RCS. [REDACTED] informed us that he pumps out the RCS about once every six weeks or as needed.

Mortality Management Area:

[REDACTED] informed us that he typically buries his mortalities in a back corner of his pasture.

Commodities Storage:

At the time of inspection, [REDACTED] hay was kept under barn and feed stored in silos.


Inspection Date: 10/19/2017

Section III – AREAS OF CONCERN

We observed no Areas of Concern at the time of the inspection.

Section IV – LIST OF APPENDICES

Appendix 1 – Photo Log – 2 photos taken 10/19/17

Appendix 1

Photograph Log



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: [REDACTED]		
City: Loranger	County/Parish: Tangipahoa	State: Louisiana



Photo File Name: DSCN6120.JPG

Date of Photo: 10/19/17

Time of Photo: 1:15 P.M.

Photographer: Collin Martin

Description: Photo taken facing west toward dewatering equipment.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: [REDACTED]		
City: Loranger	County/Parish: Tangipahoa	State: Louisiana



Photo File Name: DSCN6122.JPG

Date of Photo: 10/19/17

Time of Photo: 1:16 P.M.

Photographer: Collin Martin

Description: Photo taken facing north towards pipe which would receive a discharge if wastewater levels reached high enough.