

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	04/27/2026	Time	09:45
		Operator Representative	McCann Resources, Inc		
Operator Info	McCann Resources, Inc 1613 West 6th Street Bartlesville, OK 740033404 Phone: 918-337-4747	Inventory ID	OS5929000		
		API Well No			
		Lease Name	Whtimire		
		Well ID	11-B		
Location	NE 04 27N 11E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.847932	Longitude	-96.123611		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	McCann Resources, Inc		
Inspect No.		Date Last MIT	11/25/2019	Last Test Result	Acceptable
Casing	5.5	Tubing	2.375	USDW	280
Monitoring Device Elected	N	Tubings		Annulus	
Monitoring Device FLM Canister Pressure		Fittings	N	N	Max Pressure 250
Lease Status	Inactive	Actual Pressure	0	0	Max Volume 0
Barrel Monitor Hooked Up?	N	Determined?	Other	Other	Max Inj Units Barrels Per Month
Barrel Fluid Level (%)		Static Fluid Level			
Flowline Hooked Up?	Y	Determined?			
Injecting	N	Injection Rate (bpd)			
Inspection Comments	Well OS5929000 was connected but not injecting at the time of the inspection. The injection valve lineup was open but the lease was inactive. There was no pressure on the tubing or annulus. 1" fittings on the tubing prevented observance of the fluid level. An annulus fluid level was attempted but the echometer displayed an immediate fluid kick and repeat which indicated a fluid level very near the surface which was to be expected with a packer in place. The well was overdue for MIT.				
Inspector Signature	MATTHEW ALLEN Digitally signed by MATTHEW ALLEN Date: 2026.04.29 13:29:19 -05'00'				
Supervisor Signature	JEANNE ECKHART Digitally signed by JEANNE ECKHART Date: 2026.04.29 14:04:48 -05'00'				

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.847932, -96.123611		
City: Bowring	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010855

Orientation: NNE

Date of Photo: 04/27/2026

Time of Photo: 9:43AM

Latitude: 36.847932

Longitude: -96.123611

Photographer: Matthew Allen

Description: This was well OS5929000 at the time of the inspection. At the time of the inspection, the well was connected but not injecting. The well was overdue for MIT.